




STAMP Tag Deploying Form

 3. 4. 5. 	Tagged by:		
6.	Main Material of Construction: What is the wreckage material? Wood Steel Iron Fiberglass Check the following boxes if these details	Skip the following questions if not wooden wreckage If the wreckage is wood, does it appear to be: Hand hewn Machine Cut	
THE PROPERTY OF THE PROPERTY O	are present on the wreckage: Treenails Square Spikes Round Spikes Other Check the following boxes if the materials are present on the wreckage: Wood Iron Copper Steel	Look at the images on the instruction sheet and give your best guess on what part of the shipwreck you believe you found.	

7.	Deterioration: What does the level of deterioration seem to be?		
	☐ No deterioration ☐ Partially deteriorated ☐ Heavily deteriorated		
8.	Exposure: Check the best choice for how exposed the wreckage is: Completely exposed Partially exposed Nearly covered		
9.	Directions: \(\frac{1}{2} - \frac{34}{4}\) miles North of the Heatcoque Ctate Park boundry - On Federal park land		
	Estimated distance from the high tide line: Delow		
	beach zone behind primary dune		
	GPS coordinates:		
	Latitude: 38,25125° N Longitude: 75,1292,2° W		
12.	Length/Width/Thickness of timber:		
	Length: 8' (//) Width: - (10) Thickness: (10)		
	Orientation: N-5		
	Diameter of wooden fasteners: / Nell (_)		
	Distance between 2 fasteners:		
13.	Distance between 2 fasteners:(_) Pictures:(Name/Id#)		
	(continue on back)		
14.	Comments: Attached photo is courtesy of Mr. Edward Mt Cawley. Ms. Zarina Mc Cawley is providing scale.		



STAMP Tag #0001 Photo courtesy Mr. Edward McCawley. Ms. Zarina McCawley is providing scale.