

CARR - 679

910 MEDFORD ROAD

late 19th century

Medford

private

910 Medford Road presents a mid-to-late 19th century house type that follows the basic format of the regional farmhouse style, i.e. two stories, L-shaped plan, and gable roof. The distinguishing characteristic of this type is its four bay main facade with entrances in both of the central bays (instead of the three or five bay main facade with a central entrance). This house also retains its excellent sawn-wood ornamentation along the cornices and gable ends.



DEPARTMENT OF PLANNING AND DEVELOPMENT  
225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

3/6

SURVEY NUMBER: CARR-679

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: New Windsor

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: residence

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good ( )  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT: late 19th century (before 1877)

COUNTY: CARROLL

TOWN: Medford

LOCATION: 910 Medford Road

COMMON NAME:

FUNCTIONAL TYPE:

OWNER: Mrs. Thomas J. Talbot

ADDRESS: 910 Medford Road  
New Windsor MD 21776

ACCESSIBILITY TO PUBLIC:  
Yes ( ) No (X) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam (X) Balloon ( )
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle (X) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells (X) Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: 2

Number of Bays: 4x2

Approximate Dimensions: \_\_\_\_\_

Entrance Location: 2 central bays

THREAT TO STRUCTURE:  
No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

excellent Vict-style sawn-wood ornamentation at cornice, gable ends  
6/6 sash windows  
imitation brick asphalt siding



RELATED STRUCTURES: (Describe)

frame chicken coop  
shed

STATEMENT OF SIGNIFICANCE:

representative mid-to-late 19th century house type with 4-bays facade & double entrance

REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas: Mary Horn  
m 45 p. 205

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:



U.S.G.S. MAP  
NEW WINDSOR, MD.  
1:24000 SCALE



1. CARR-679 910 MEDFORD ROAD
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. South and east elevation (camera facing northwest)
7. 1/1