

GAITHERSBURG HISTORIC SITES SURVEY FIELD SHEET

ADDRESS 9 WALKER AVENUE  
County: Montgomery  
Gaithersburg

MHT # M-21-28  
LIBER -, FOLIO -

SURVEY # 118  
LOT -, BLOCK -

OWNER: Paul/Megan Lembesis  
ADDRESS: same  
CITY: same

PRESENT USE: residence  
ORIGINAL USE: residence  
BUILDER: -

STYLE: Late Victorian

DATE BUILT: c.1905

PHYS. COND: good

GENERAL DESCRIPTION

STRUCTURAL SYSTEM:

FOUNDATION: brick  
WALL STRUCTURE: Balloon  
WALL COVERING: modern siding covering wood

ROOF CONSTRUCTION:

ROOF STRUCTURE: Wood Truss  
ROOF COVERING: asphalt shingle  
ROOF STYLE: gable  
EAVES: boxed cornice  
CHIMNEYS: one, interior

APPENDAGES:

ADDITIONS: rear  
ELLS: -  
PORCHES: front  
SUPPORTS: turned post  
OUTBUILDINGS: -

STORIES: 2 1/2

BAYS: 2 x 4

APPROX DIMENSION: 25 x 39

WINDOWS:

TYPE: d.h.s.  
LIGHTS: 2/2  
BAY WINDOWS: -  
SIDE BY SIDES: -  
GABLE TYPES: diamond

ENTRANCES:

LOCATION: 1st  
DESCRIPTION: 2/3 glass panel

THREAT: none

SURROUNDINGS: residential

M:21-28

118

DESCRIPTION: This 2 1/2 storey front gabled house has a full width porch which wraps to the left. The porch is supported by six squared chamfered turned posts with brick piers and decorative corner brackets, plain balusters and railing. There is a one-light transom above the main door. The front gable has a diamond-shaped window.

Right elevation has side-by-side d.h.s. 1/1 in front bay; all other windows are 2/2 in each bay first and second storey. The side gable has a boxed cornice with return, plain frieze and one 2/2 d.h.s. The left elevation has symmetrical 2/2 fenestration and identical side gable to right elevation. Rear elevation has an addition with modern 12-light bay window and entrance door. There is a corbel capped interior chimney located on the sloop of the rear main roof.

According to Mr. Mark Kelsch, past renter, the rear porch was added in 1980 and the house sided around 1975. There was a fire in the house approximately 15 years ago. The house was originally covered in German siding, then stuccoed which was removed when modern siding was added. There are two garages located to the left rear of the property.

Recorded by:

C. Kozar

October 24, 1981

Historic Inventory Task Force