

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC

**Dandy Hall**

AND/OR COMMON

**2 LOCATION**

STREET & NUMBER

100-~~102~~ North Liberty Street

CITY, TOWN

Centreville

\_\_\_ VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

**3 CLASSIFICATION**

**CATEGORY**

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

**OWNERSHIP**

- PUBLIC
- PRIVATE
- BOTH
- PUBLIC ACQUISITION**
- IN PROCESS
- BEING CONSIDERED

**STATUS**

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE**
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

**PRESENT USE**

- AGRICULTURE
- COMMERCIAL
- EDUCATIONAL
- ENTERTAINMENT
- GOVERNMENT
- INDUSTRIAL
- MILITARY
- MUSEUM
- PARK
- PRIVATE RESIDENCE
- RELIGIOUS
- SCIENTIFIC
- TRANSPORTATION
- OTHER: office

**4 OWNER OF PROPERTY**

NAME

Sidney G. Ashley

Telephone #:

STREET & NUMBER

107 South Commerce St.

CITY, TOWN

Centreville

\_\_\_ VICINITY OF

STATE, zip code

Maryland 21617

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE,

REGISTRY OF DEEDS, ETC Queen Anne's County Courthouse

Liber #: CWC 142

Folio #: 453

STREET & NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

\_\_\_ FEDERAL \_\_\_ STATE \_\_\_ COUNTY \_\_\_ LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

QA-317

<b>CONDITION</b>		<b>CHECK ONE</b>	<b>CHECK ONE</b>
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED      DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Dandy Hall is located on the northwest corner of Liberty Street and Water Street in Centreville. It is a two story frame building with a pitched gable roof, two story open porch on the front facade, facing Liberty Street, and a two story frame lean-to addition to the rear.

The first floor of the front facade is primarily a store front, with large shop windows flanking a recessed entrance door. A second door at the north end of this facade opens into a narrow stair hall leading up to a second floor apartment. The latter entrance has a paneled Victorian door with a two-light transom above. On the second floor, there is a door opening onto the upper porch, with one large 4/4 window to the left of the door and two to the right. The porch is supported by square posts with simple molded bases and caps. The first floor posts rest on high concrete supports. The second floor porch is enclosed with a plain ballustrade.

On the south gable of the original section, there are 2/2 windows flanking a flush brick

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

- |   |  |   |   |  |
|---|--|---|---|--|
| <input type="checkbox"/> PREHISTORIC          | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC  | <input type="checkbox"/> COMMUNITY PLANNING     | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION            |
| <input type="checkbox"/> 1400-1499            | <input type="checkbox"/> ARCHEOLOGY-HISTORIC     | <input type="checkbox"/> CONSERVATION           | <input type="checkbox"/> LAW                    | <input type="checkbox"/> SCIENCE             |
| <input type="checkbox"/> 1500-1599            | <input type="checkbox"/> AGRICULTURE             | <input type="checkbox"/> ECONOMICS              | <input type="checkbox"/> LITERATURE             | <input type="checkbox"/> SCULPTURE           |
| <input type="checkbox"/> 1600-1699            | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION              | <input type="checkbox"/> MILITARY               | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799            | <input type="checkbox"/> ART                     | <input type="checkbox"/> ENGINEERING            | <input type="checkbox"/> MUSIC                  | <input type="checkbox"/> THEATER             |
| <input checked="" type="checkbox"/> 1800-1899 | <input checked="" type="checkbox"/> COMMERCE     | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY             | <input type="checkbox"/> TRANSPORTATION      |
| <input checked="" type="checkbox"/> 1900-     | <input type="checkbox"/> COMMUNICATIONS          | <input type="checkbox"/> INDUSTRY               | <input type="checkbox"/> POLITICS/GOVERNMENT    | <input type="checkbox"/> OTHER (SPECIFY)     |
|   |  | <input type="checkbox"/> INVENTION              |   |  |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

# 9 MAJOR BIBLIOGRAPHICAL REFERENCES

QA-317

CONTINUE ON SEPARATE SHEET IF NECESSARY

## 10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

## 11 FORM PREPARED BY

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

7/7/80

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville

STATE

Maryland

Field Notebook QA-IX; Recorded May 24, 1979.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

## CONTINUATION SHEET

## 7.1 DESCRIPTION

stove chimney on the first floor, a 2/2 to the left of the chimney on the second floor and a 4/4 to the right, and a pair of louvered vents in the upper gable. A pair of "transom" windows between the first and second floor do not line up with the other openings. There is a single paneled door at the extreme left side on the first floor. The rear lean-to is only one bay wide, with a door on the first floor and a 2/2 window on the second floor.

The north gable has asymmetrical fenestration, with all of the openings shifted toward the rear of the building, in large part due to the stair hall. On the first floor, there is a small six-light sash near the center and a 6/6 window to the rear. On the second floor there is a six-light sash near the center and two 6/6 windows to the rear. A louvered vent in the upper gable replaced an earlier semi-circular vent.

The exterior is covered with a variety of siding materials. The north gable is covered with vertical board and batten, the south gable with asbestos shingle. The first floor of the front facade has plain horizontal weatherboard siding, the second floor is covered with German siding. The eaves are boxed in

## CONTINUATION SHEET

## 7.2 DESCRIPTION

and finished with a crown mold. The tin roof is applied over earlier wood shingles. The interior has been completely renovated numerous times over the years.

BELVEDERE AVE.

CHESTERFIELD AVE. MD. 304

JOSEPH R RICHARDSON & FRIDA C.W. SMITH CWC 107/170

P. 81

GEORGE E. ICKES, ETAL CWC 93/659

ALICE JEWELL TSP 26/706 P. 80

W. HARMAN EATON TSP 62/118 P. 83

ELIZABETH TUTTLE CWC 25/41 R. 41

WILLIAM R. JUMP CWC 77/598 P. 81

STREET

CARLTON ROE TSP 80/9 R. 79  
HELEN ROE, ETAL CWC 26/480 R. 78  
DAVID B. SKINNER R. 77 CWC 107/478  
E.J. MITCHELL CWC 20/480 R. 76  
MIRIAM CHAMBERS TSP 27/9 PARCEL A  
SYDNEY G. ASHLEY CWC 142/485 P. 74  
JAMES SEWARD TSP 27/278 R. 72

SYDNEY G. ASHLEY MWM 143/468 P. 89  
SYDNEY G. ASHLEY MWM 143/468 P. 71

MARY E. TURNER CWC 125/434 P. 84  
ELIZABETH H. COLLINS CWC 37/11 R. 88  
LESTER C. LEONARD, JR. CWC 56/498 P. 87  
LESTER C. LEONARD CWC 80/81 P. 87

STREET

GOODWILL FIRE CO. INC. ASS. JR. 17/280 R. 40

GOODWILL FIRE CO. INC. CWC 25/172 P. 89

JOHN W. HURT, JR. No DAWYNS MARKET CWC 54/54 P. 36

CENTREVILLE L. STREET LTD. PA CWC 142/698 P. 87

GA-317 DANDY HALL

COUNTY JAIL P. 70

LIBERTY

WATER

E. U. GRADY MWM 1/597 P. 63  
ALEX L. GOLDSTEIN CWC 134/73 P. 64  
V.A. DOWNES, JR. CWC 116/372 P. 65  
JAMES H. BARTON CWC 7/587 P. 66  
WILLIAM F. MAYER CWC 34/665 P. 67  
SHIRLEY GOLDSTEIN CWC 19/52 P. 68  
H. GOLDSTEIN CWC 19/55 P. 69  
H. GOLDSTEIN JR. ASO 5/232 P. 49  
CENTREVILLE NATIONAL BANK OF MD. CWC 25/62 P. 50  
CENTREVILLE NATIONAL BANK J.C. 4/378-573-334 P. 51

LAWYERS ROW

COURT HOUSE P. 48

BROADWAY

STATE OF MARYLAND (BOARD OF PUBLIC WORKS) CWC 132/443 P. 54

FARMERS NATIONAL BANK CWC 117/24 P. 52

BAY PUBLISH CORP CWC 112/57 P. 50

FARMERS NATIONAL BANK CWC 117/22 P. 51

JR. SMITH, JR. TSP 80/436 P. 53

M. BIERMAN, JR. CWC 24/27 P. 54

FARMERS NATIONAL BANK CWC 117/20 P. 51

LEONORA M. MURPHY CWC 137/505 P. 55  
CLIN. PIPPIN JFR 10/508.1. O.C. REC 1256 P. 56


JAMES M. CHANCE TSP 23/485 P. 52

DEPT OF ASSESSMENTS & TAXATION TAX MAP DIVISION  
REVISED TO JUNE 1 '79 MWM150

COMMERCE


	Maryland Department of Assessments and Taxation	Go Back
	QUEEN ANNE'S COUNTY	View Map
	Real Property Data Search	New Search

District - 03 Account Number - 001083



Property maps provided courtesy of the Maryland Department of Planning ©2004.  
For more information on electronic mapping applications, visit the Maryland Department of Planning web site at [www.mdp.state.md.us/webcom/index.html](http://www.mdp.state.md.us/webcom/index.html)

QA-317  
Dandy Hall  
100 N. Liberty St.  
Centreville  
Centreville Quad.  
Queen Anne's Co.



QA-317  
Dandy Hall

Mary McCarthy  
Spring/Summer 2003  
Digital color photo on file at MHT





QA-317 Dandy Hall  
*100* ~~102~~ North Liberty St.  
Centreville, Maryland  
Orlando Ridout V 1980  
View from Northeast



QA-317 Dandy Hall  
100 ~~102~~ North Liberty St.  
Centreville, Maryland  
Orlando Ridout V 1980  
View from Southeast