



STAMP Tag Deploying Form

- 1. Tagged by: DOUG SELZER
- 2. Tag Number(s) (####): 0048
- 3. Date: 4/07/2024 Time: 12:40 am pm
Tide level: High Medium Low
- 4. Name of wreck (if known): _____
- 5. Description: How did the wreckage reach its present position?
 Float Uncovered Other _____

6. **Main Material of Construction:** What is the wreckage material?

Wood Steel Iron Fiberglass

Check the following boxes if these details are present on the wreckage:

Treenails Square Spikes
 Round Spikes Other **ROUND SPIKE HOLES + IRON**

Check the following boxes if the materials are present on the wreckage:

Wood Iron Copper Steel

Skip the following questions if not wooden wreckage

If the wreckage is wood, does it appear to be:

Hand hewn Machine Cut
 Both? Other

Look at the images on the instruction sheet and give your best guess on what part of the shipwreck you believe you found.

GUNNEL - possible

7. **Deterioration:** What does the level of deterioration seem to be?
 No deterioration Partially deteriorated Heavily deteriorated

8. **Exposure:** Check the best choice for how exposed the wreckage is:
 Completely exposed Partially exposed Nearly covered

9. **Directions:** BEACH SHORELINE

10. **Estimated distance from the high tide line:**

below _____ (ft) above _____ (ft)
 beach zone behind primary dune

11. **GPS coordinates:**

Latitude: 38.21523° N Longitude: 75.14622° W

12. **Length/Width/Thickness of timber:**

Length: 50" () Width: 12" () Thickness: 4" ()

Orientation: N-S

Diameter of wooden fasteners: 1" ()

Distance between 2 fasteners: 15" ()

13. **Pictures:** _____ (Name/Id#)

_____ (continue on back)

14. **Comments:** _____

Please send this completed form to susan.langley@maryland.gov with photos. Scans of the form or legible photos are acceptable or mail to: Dr. S. Langley, Maryland Historical Trust, 100 Community Place, Crownsville, MD 21032.



