

**Addendum to  
Maryland Historical Trust  
Maryland Inventory of  
Historic Properties Form**

Inventory No. PG:85A-57

Page 1 of 1

**Name of Property: SHA Small Structure No. 16178X0**

**Location: MD 381 over Timothy Branch, Prince George's County**

---

SHA Small Structure No. 16178X0, MD 381 over Timothy Branch, was a concrete slab small structure built using the Maryland State Roads Commission's Standard Plan design from circa 1912. It was determined to be not eligible for the National Register of Historic Places by SHA on October 15, 2001, and MHT concurred with that determination on December 15, 2001.

SHA reported in September 2011 that the small structure had been destroyed during the flooding caused by Tropical Storm Lee on September 7 and 8, 2011. It was replaced temporarily with corrugated metal pipes during that time.

MARYLAND HISTORICAL TRUST  
NR-ELIGIBILITY REVIEW FORM

NR Eligible: yes \_\_\_  
no \_\_\_

Property Name: Small Structure No. 16178X0 Inventory Number: PG: 85A-57

Address: MD 381 over Timothy Branch City: Brandywine Zip Code: \_\_\_\_\_

County: Prince George's County USGS Topographic Map: Brandywine

Owner: MD SHA

Tax Parcel Number: N/A Tax Map Number: N/A Tax Account ID Number: N/A

Project: SP013B45 Agency: State Highway Administration(SHA)

Site visit by MHT Staff: \_\_\_ no X yes Name: Liz Buxton Date: October 15, 2001

Eligibility recommended \_\_\_ Eligibility not recommended X

Criteria: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D Considerations: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D \_\_\_ E \_\_\_ F \_\_\_ G \_\_\_ None

Is the property located within a historic district? X no \_\_\_ yes Name of district: \_\_\_\_\_

Is district listed? X no \_\_\_ yes Determined eligible? \_\_\_ no \_\_\_ yes District Inventory Number: \_\_\_\_\_

Documentation on the property/district is presented in: Project review and compliance files

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*

Structure No. 16178X0 is a 13-foot, 6-inch long concrete slab that spans the Timothy Branch in Prince George's County. The structure consists of a single span, a solid parapet without incising and standard abutments without horizontal scoring. The actual date of construction is not known, over, it is similar to the 1912 State Roads Commissions Standard design.

The historic context report, Small Structures in Maryland's Roadways, indicates that concrete slabs built between 1912-1933 were the most widely used small structure. Unaltered concrete slab structures built according to the standard plans could be eligible for the National Register under Criteria C if all character-defining elements are present. Although the structure retains the original parapet and abutments, the structure is significantly deteriorated. In addition, metal guardrails have been added on both roadway approaches that has compromised the integrity of the structure. Therefore, Structure No. 16178X0 is not eligible for listing on the National Register of Historic Places.

Prepared by: Liz Buxton

Date Prepared: October 15, 2001

<b>MARYLAND HISTORICAL TRUST REVIEW</b>	
Eligibility recommended ___	Eligibility not recommended <u>X</u>
Criteria: ___ A ___ B ___ C ___ D	Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G ___ None
Comments: _____	
<u>Andrew Lewis</u>	<u>12/12/01</u>
Reviewer, Office of Preservation Services	Date
<u>[Signature]</u>	<u>12/15/01</u>
Reviewer, NR program	Date

**Addendum to  
Maryland Historical Trust  
Maryland Inventory of  
Historic Properties Form**

Inventory No. PG:85A-57

Page 1 of 1


Name of Property: Small Structure No. 16178X0

Location: MD 381 over Timothy Branch, Brandywine, MD

---

Small Structure No. 16178X0 is no longer extant. Flooding associated with remnants of Tropical Storm Lee caused a loss of fill around Small Structure No. 16178X0 resulting in the abutments rotating and the slab collapsing between the abutments. SHA completed repairs on September 21, 2011 that involved the removal of the failed structure.

PG:85A-57  
Small Structure No. 16178X0  
Brandywine Road (MD 381) over Timothy Branch  
Brandywine Quadrangle





PG: 85A-57

Small Structure No 16178X0

L. Buxton

Nov 2001

MD 5400

Looking West

Processing by  
**Kodak**  
NOV. 2001 G

Processing by  
**Kodak**  
NOV. 2001 G

Process  
**Kod**  
NOV. 2

1 of 2



10 15 01

PG: 85A-57

Small structure NO. 16178XU

L. Buxton

Nov 2001

MD STPD

Looking N.V

2 of 2

Processing by  
**Kodak**  
NOV. 2001 G

Processing by  
**Kodak**  
NOV. 2001 G