B-831
1405 Eutaw Place
Block 0380 Lot 002
Baltimore City
Baltimore West Quad.



GIS data Courtesy of
the City of Baltimore, MOIT/EGIS



Front Before B-831

B-831

rear- before

MAR 1983

Kodak

paper & equipment used
to produce this picture

MAR 1983

Kodak

paper & equipment used
to produce this picture

Kodak
paper & equipment used
to produce this picture

MAR 1983

Kodak
paper & equipment used
to produce this picture

MAR 1983

Kodak
paper & equipment used
to produce this picture

MAR 1983

188-B

Front

B-831

Work in progress

B-831

Front

During work

B-831

Front

During work

Front + part of side

during work

B-831

B-831

Front during

showing underlayment Part of

rebuilding mansard - ply wood (exterior grade and tar paper)

B-831

Bay Area During

showing extent of removal (entire)
of built-in gutter

10

Side showing remove
gutter and one area of brick replacement

B-83

Side view from front toward bay showing replacement of supports for new built-in gutter

Kodak
paper & equipment used to produce this picture
MAR 1983

Kodak
paper & equipment used to produce this picture
MAR 1983

B-831



B-831

Side toward front

Showing replacement of support for built-in gutter. Also show part of old gutter and slates. All of old gutter subsequently removed. All slates removed, and replaced after repairs to mansard.

13.

B-831

Rear view

Showing mansard and dormer repairs

14.

B-831

1405 Eutaw Place
Baltimore City, Md.

15.

Front View after B-831

Kodak

paper & equipment used
to produce this picture

MAR 1983

Kodak

paper & equipment used
to produce this picture

MAR 1983

Kodak

MAR 1983