

POPPLETON HISTORIC STUDY

B-2544

MAG #0425445504

<u>Block</u>	<u>Lot</u>	<u>Address</u>	<u>Approximate age</u>				
198	28-29	12-14 N. Carey Street	<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>

The 1896 map shows the building as "The Concord Club."

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>			
A	Significant-save	good	fair	poor	bad
B	Quality-Indiv./groups-save	good	fair	poor	bad
<u>C</u>	Important to street/groups	good	<u>fair</u>	<u>poor</u>	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

This pair of houses has been damaged by removal of its doors and addition of formstone, but rehabilitation should be considered in order to maintain something of the setting of Linden Place. Superficially the houses seem in fair condition.

Environmental context:

Wide but not busy street; needs large street trees. Scale of these houses is strange, almost industrial warehouse-like. It is not bad in relation to the old institute building across the street.

(See photo attached to lots 30-32, 18-22 N. Carey Street.)

B-2544
12-14 N. Carey Street
Block 198 Lots 028-029
Baltimore City
Baltimore West Quad.

