

BA-621  
Bedlam  
north side of Monkton Road  
St. James Corners

before 1850

Possibly the L. Merryman house on the 1850 map, the building is not shown on the 1877 atlas. Recently restored, this clapboard-covered vernacular frame house of two stories has interior chimneys in the ends of the gable roof.