

BA-974

WESTERN RUN ROAD IRON BRIDGE (SITE) - c. 1895 - Western Run Road over Black Rock Run, crossing over into District 5. Baltimore County Bridge No. 3. Possibly put up by the former turnpike company following the storm of September 6, 1895, when a covered bridge was washed out. Manufactured by Wrought Iron Bridge Company, Canton, Ohio. Damaged in the flood following tropical storm "Agnes" in June of 1972. Further damaged by truck accident, November 19, 1973. This was a four-panel Pratt, wrought-iron, through-truss bridge with inclined end posts, 99-foot span, 17 feet high, with timber flooring, stone abutments; it had been strengthened in 1970. Replaced in 1974 by an Acrow Panel Bridge (Bailey Bridge); concrete pilasters added in October, 1976.

BA-974
Western Run Road Iron Bridge, site
Western Run Road over Black Rock Run, Butler
Hereford Quadrangle

