

PRINCE GEORGE'S COUNTY
HISTORIC SITE SUMMARY SHEET

Survey #: P.G. #68-36

Building Date: 1924, 1955

Building Name: Mt. Rainier United Methodist Church

Location: 35th and Bunker Hill Streets, Mt. Rainier (3501 Bunker Hill Rd.)

Private/Church/Occupied/Good/Accessible

Description:

The Mt. Rainier United Methodist Church is a two-part building, the whole having an "L" shaped plan. The rectangular north wing, constructed of random stone, dates to 1924. The south brick wing, set perpendicular to the north wing, dates to 1955. The older block is three bays on its north, main gable end. Three double entrance doors are set high above street level, reached by a flight of stairs approaching from the east and west to the high entry porch. The doors are surmounted by a rectangular transom, a wide frieze with a heavy crown-molded cornice, and a rectangular stone tablet. The porch and entrance doors are sheltered by a two-story portico supported on Tuscan Doric columns, surmounted by an entablature and a triangular pediment with a centered circular window. Located at the northwest corner of the facade is a corner stone engraved "Mt. Rainier M.E. Church South 1924." The east and west facades have three high round-arch stained glass windows. The long, brick circa 1955 wing is attached to the main block at the south end. The wing is three stories in height, three bays on the east and west-facing gable ends, by eight bays on the long south side. A high bell tower is attached where the southeast corner of the main block meets the brick wing. The bell tower has a two-story square brick base with a round-arch double entry door in the north facade.

Significance

The Mt. Rainier United Methodist Church is significant for its monumental, Classical Revival architecture. It is an institution in the community, both for its long history there and for the prominence of its structure. The congregation began meeting in 1903, as a mission of the Hyattsville Methodist Episcopal Church. The church incorporated in 1919 as the Mt. Rainier Methodist Episcopal Church South, and acquired the lot at the corner of Bunker Hill and 35th Streets from John C. Yost. In 1924 construction began on a permanent structure, with Rossel E. Mitchell of Washington, D.C. as the architect. The building is outstanding for its blue-grey, random fieldstone walls, its monumental entrance portico and large, round-arch stained glass windows. In 1955 the brick wing was added to the south of the stone structure, more than doubling its size.

Acreage: 26,374 square feet

Magi No.

DOE yes no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (Indicate preferred name)

historic Mt. Rainier United Methodist Church

and/or common

2. Location

street & number 3501 Bunker Hill Road not for publication

city, town Mt. Rainier vicinity of congressional district 5

state Maryland county Prince George's

3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military
			<input type="checkbox"/> museum
			<input type="checkbox"/> park
			<input type="checkbox"/> private residence
			<input checked="" type="checkbox"/> religious
			<input type="checkbox"/> scientific
			<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Mt. Rainier United Methodist Church

street & number 3501 Bunker Hill Road telephone no.:

city, town Mt. Rainier state and zip code MD 20712

5. Location of Legal Description

courthouse, registry of deeds, etc. Prince George's County Courthouse liber 138

street & number Main Street folio 114

city, town Upper Marlboro state MD 20712

6. Representation in Existing Historical Surveys

title NA

date federal state county local

depository for survey records Historic Preservation Commission, Room 4010, CAB

city, town Upper Marlboro state MD

7. Description

Survey No P.G. #68-36

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Mt. Rainier United Methodist Church is a two-part building, the whole having an "L" shaped plan. The north wing, rectangular in plan, constructed of random laid stone, dates to 1924. The south brick wing, rectangular in plan, set perpendicular to the north wing, dates to 1955.

The church stands on the northeast corner of the intersection of Bunker Hill and 35th Streets. The older main block is three bays on its north, main gable end. Three double entrance doors are set high above street level and are reached by a flight of stairs approaching from the east and west to the high entry porch in front of the doors. The doors are surmounted by a rectangular transom, and a wide frieze with a heavy crown-molded cornice. There is a rectangular stone tablet above each door, and at second story level, a 1/1 double-hung sash stained glass window.

The porch and entrance doors are sheltered by a two-story portico supported on Tuscan Doric columns and surmounted by an entablature and a triangular pediment with a centered circular window. The pediment, and the upper gable on the main block are enclosed by a modillioned cornice and the wall surface is stuccoed. Located at the northwest corner of the facade, at approximately five feet above foundation level is a corner stone, engraved "Mt. Rainier M.E. Church South 1924."

The two-story ca. 1924 block is laid in roughly finished, random fieldstone, with convex mortar joints. The gable roof is slate covered. The modillioned cornice continues on the east and west sides of the building.

The four bay east facade has three high round-arch stained glass windows. Corresponding small rectangular windows are set at foundation level. There is a side-entry in the north bay. The five bay west facade is similar to the east with the exception of an extra south bay of 6/6 sash windows at foundation, first and second story level.

MARYLAND HISTORICAL TRUST
STATE HISTORIC SITES INVENTORY FORM

68-316
Survey No. P.G.#68-31

Description (continued)

Section 7 Page 2

The long, brick circa 1955 wing is set perpendicular to the main block, attached to it at the south end. The wing is three stories in height, with a gable, slate roof. It is three bays on the east and west-facing gable ends, by eight bays on the long south side. Windows are 6/6 sash, surmounted by flat arches.

A high bell tower is attached where the southeast corner of the main block meets the brick wing. The bell tower has a two-story square brick base with a round-arch double entry door in the north facade. A heavy modillioned cornice encircles the tower above the second story. It is surmounted by a small rectangular wooden tower, with round-arch louvered openings flanked by pilasters and surmounted by a triangular pediment, in each face. The tower has a circular top section with a domed cap surmounted by a cross.

The church yard is encircled by a low retaining wall of the same fieldstone as the main block, surmounted by castellations. A large asphalt parking lot is to the south (rear) of the building. The rectory, a brick, ca. 1920's building, is south of the parking lot, fronting on 35th Street.

The sanctuary is a large rectangular room located in the original main block, and takes up the majority of the main floor. The curving pews, in a double row facing south, to the altar, are original. The wainscoting, of vertical rectangular panels, stained the same color as the pews, is also original. The wide, one-step surround around the stained glass windows is of the same wood. A curved balcony at the north end of the room echoes the curve of the pews. The high ceiling has an elaborate plaster cornice. Tudor-arch brass lantern fixtures hang from the ceiling. Two flat, rectangular pilasters flank the high rectangular opening over the altar.

8. Significance

Survey No.

P.G. #68-36

Period	Area of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input checked="" type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input checked="" type="checkbox"/> other (specify)
				local history

Specific dates 1924, 1955 **Builder/Architect** Rosel E. Mitchell architect

check: Applicable Criteria: A B C D R.E. Milor and Co., builder
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Mt. Rainier United Methodist Church is significant for its monumental, Classical Revival architecture. It is an institution in the community, both for its long history there and for the prominence of its structure.

The congregation began meeting in 1903, as a mission of the Hyattsville Methodist Episcopal Church, and met in a barn at what is now 37th and Upshur Streets in Mt. Rainier through 1916. In that year 26 congregants signed a petition to the Methodist Bishop of Maryland, requesting permission to reorganize as a self-supporting congregation, separate from the Hyattsville Church. The reorganized congregation, taking the name of Mt. Rainier Methodist, worshipped at Potts Hall (now Star Hall) on Rhode Island Avenue, through June 1916. They met in a tent through the summer of 1916 on the lot at Bunker Hill and 35th Streets where they eventually built their permanent building. A temporary wooden structure was constructed on the site that fall.

The church incorporated in 1919 as the Mt. Rainier Methodist Episcopal Church South, and acquired the 26,374 square foot lot at the northeast corner of Bunker Hill and 35th Streets from John C. Yost.¹ The lot is located in the subdivision called Yost's Addition to Mt. Rainier.²

In 1924 the congregation had reached 447 adult members, and construction began on a permanent church structure. Rosel E. Mitchell of Washington, D.C. was the architect commissioned. The builder was R.E. Milor and Company and the stone contractor Jaeger and Minchillo.³ The building constructed is outstanding for its blue-grey, random fieldstone walls, its monumental entrance portico and large, round-arch stained glass windows.

In 1955, with a congregation numbering near 800, the brick wing was added to the south of the original stone structure, more than doubling its size. The brick wing is also monumental in design and scale, being three stories in height, with a high southeast bell tower. The wing is in

MARYLAND HISTORICAL TRUST
STATE HISTORIC SITES INVENTORY FORM
Statement of Significance (continued)

Survey No. P.G.#68-36
Section 8 Page 2

Colonial Revival style, its bell tower with domed cap and pedimented cornice, 6/6 sash windows, returned cornice, centered circular windows in the gable ends, and slate gable roof all 20th century interpretations of Colonial style elements.

The Mt. Rainier United Methodist Church presently has a congregation of 180 members. It is opening its well maintained facility for use as a day care center and offices for local non-profit organizations, as a way to continue to serve its institutional function in the community.⁴

Notes

- 1 10th Anniversary Book, Mt. Rainier Methodist Episcopal Church, April 16, 1926. Available at the Church.
- 2 Land Records of Prince George's County, 138:114.
- 3 10th Anniversary Book.
- 4 Interview with Reverend Ralph L. Minker, Pastor, Mt. Rainier United Methodist Church, January 1987.

Chain of Title
Mt. Rainier United Methodist Church
P.G. #68-36

138:114 John C. and Emma V. Yost of Washington, D.C. to Mt. Rainier
3 Feb. 1919 Methodist Episcopal Church, South, a body corporate under
Deed Maryland law. For \$10 grantor convey a part of land Yost
 obtained from Benedict Yost Estate. 100 feet on Bunker
 Hill Road by 200 feet on 35th Street.

WAJ, JR 1:134 Benedict Yost divides real estate equally among children.
16 Oct. 1883
Wills

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. P.G. #68⁻¹³⁻36
 Magi No. 16:68-36
 DOE yes no

1. Name (indicate preferred name)

historic Mt. Rainier United Methodist Church

and/or common

2. Location

street & number 3401 Bunker Hill Road not for publication

city, town Mt. Rainier vicinity of congressional district 5

state Maryland county Prince George's

3. Classification

Category	Ownership	Status	Present Use	
<u> </u> district	<u> </u> public	<input checked="" type="checkbox"/> occupied	<u> </u> agriculture	<u> </u> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<u> </u> unoccupied	<u> </u> commercial	<u> </u> park
<u> </u> structure	<u> </u> both	<u> </u> work in progress	<u> </u> educational	<u> </u> private residence
<u> </u> site	Public Acquisition	Accessible	<u> </u> entertainment	<input checked="" type="checkbox"/> religious
<u> </u> object	<u> </u> in process	<input checked="" type="checkbox"/> yes: restricted	<u> </u> government	<u> </u> scientific
	<u> </u> being considered	<u> </u> yes: unrestricted	<u> </u> industrial	<u> </u> transportation
	<input checked="" type="checkbox"/> not applicable	<u> </u> no	<u> </u> military	<u> </u> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Mt. Rainier United Methodist Church

street & number 3401 Bunker Hill Road telephone no.:

city, town Mt. Rainier state and zip code MD 20712

5. Location of Legal Description

courthouse, registry of deeds, etc. Prince George's County Courthouse liber 138

street & number Main Street folio 114

city, town Upper Marlboro state MD 20712

6. Representation in Existing Historical Surveys

title NA

date federal state county local

depository for survey records Historic Preservation Commission, Room 4010, CAB

city, town Upper Marlboro state MD

7. Description

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Mt. Rainier United Methodist Church is a two-part building, the whole having an "L" shaped plan. The north wing, rectangular in plan, constructed of random laid stone, dates to 1924. The south brick wing, rectangular in plan, set perpendicular to the north wing, dates to 1955.

The church stands on the northeast corner of the intersection of Bunker Hill and 35th Streets. The older main block is three bays on its north, main gable end. Three double entrance doors are set high above street level and are reached by a flight of stairs approaching from the east and west to the high entry porch in front of the doors. The doors are surmounted by a rectangular transom, and a wide frieze with a heavy crown-molded cornice. There is a rectangular stone tablet above each door, and at second story level, a 1/1 double-hung sash stained glass window.

The porch and entrance doors are sheltered by a two-story portico supported on Tuscan Doric columns and surmounted by an entablature and a triangular pediment with a centered circular window. The pediment, and the upper gable on the main block are enclosed by a modillioned cornice and the wall surface is stuccoed. Located at the northwest corner of the facade, at approximately five feet above foundation level is a corner stone, engraved "Mt. Rainier M.E. Church South 1924."

The two-story ca. 1924 block is laid in roughly finished, random fieldstone, with convex mortar joints. The gable roof is slate covered. The modillioned cornice continues on the east and west sides of the building.

The four bay east facade has three high round-arch stained glass windows. Corresponding small rectangular windows are set at foundation level. There is a side-entry in the north bay. The five bay west facade is similar to the east with the exception of an extra south bay of 6/6 sash windows at foundation, first and second story level.

MARYLAND HISTORICAL TRUST
STATE HISTORIC SITES INVENTORY FORM

Survey No. P.G.#68A36

Description (continued)

Section 7 Page 2

The long, brick circa 1955 wing is set perpendicular to the main block, attached to it at the south end. The wing is three stories in height, with a gable, slate roof. It is three bays on the east and west-facing gable ends, by eight bays on the long south side. Windows are 6/6 sash, surmounted by flat arches.

A high bell tower is attached where the southeast corner of the main block meets the brick wing. The bell tower has a two-story square brick base with a round-arch double entry door in the north facade. A heavy modillioned cornice encircles the tower above the second story. It is surmounted by a small rectangular wooden tower, with round-arch louvered openings flanked by pilasters and surmounted by a triangular pediment, in each face. The tower has a circular top section with a domed cap surmounted by a cross.

The church yard is encircled by a low retaining wall of the same fieldstone as the main block, surmounted by castellations. A large asphalt parking lot is to the south (rear) of the building. The rectory, a brick, ca. 1920's building, is south of the parking lot, fronting on 35th Street.

The sanctuary is a large rectangular room located in the original main block, and takes up the majority of the main floor. The curving pews, in a double row facing south, to the altar, are original. The wainscoting, of vertical rectangular panels, stained the same color as the pews, is also original. The wide, one-step surround around the stained glass windows is of the same wood. A curved balcony at the north end of the room echoes the curve of the pews. The high ceiling has an elaborate plaster cornice. Tudor-arch brass lantern fixtures hang from the ceiling. Two flat, rectangular pilasters flank the high rectangular opening over the altar.

8. Significance

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input checked="" type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculptu
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input checked="" type="checkbox"/> other (specify)
				local history

Specific dates 1924, 1955 **Builder/Architect** Rossel E. Mitchell architect

check: Applicable Criteria: A B C D R.E. Milor and Co., builder and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Mt. Rainier United Methodist Church is significant for its monumental, Classical Revival architecture. It is an institution in the community, both for its long history there and for the prominence of its structure.

The congregation began meeting in 1903, as a mission of the Hyattsville Methodist Episcopal Church, and met in a barn at what is now 37th and Upshur Streets in Mt. Rainier through 1916. In that year 26 congregants signed a petition to the Methodist Bishop of Maryland, requesting permission to reorganize as a self-supporting congregation, separate from the Hyattsville Church. The reorganized congregation, taking the name of Mt. Rainier Methodist, worshipped at Potts Hall (now Star Hall) on Rhode Island Avenue, through June 1916. They met in a tent through the summer of 1916 on the lot at Bunker Hill and 35th Streets where they eventually built their permanent building. A temporary wooden structure was constructed on the site that fall.

The church incorporated in 1919 as the Mt. Rainier Methodist Episcopal Church South, and acquired the 26,374 square foot lot at the northeast corner of Bunker Hill and 35th Streets from John C. Yost.¹ The lot is located in the subdivision called Yost's Addition to Mt. Rainier.²

In 1924 the congregation had reached 447 adult members, and construction began on a permanent church structure. Rossel E. Mitchell of Washington, D.C. was the architect commissioned. The builder was R.E. Milor and Company and the stone contractor Jaeger and Minchillo.³ The building constructed is outstanding for its blue-grey, random fieldstone walls, its monumental entrance portico and large, round-arch stained glass windows.

In 1955, with a congregation numbering near 800, the brick wing was added to the south of the original stone structure, more than doubling its size. The brick wing is also monumental in design and scale, being three stories in height, with a high southeast bell tower. The wing is in

MARYLAND HISTORICAL TRUST
STATE HISTORIC SITES INVENTORY FORM
Statement of Significance (continued)

Survey No. ⁻¹⁸⁻ P.G.#68_A36
Section 8 Page 2

Colonial Revival style, its bell tower with domed cap and pedimented cornice, 6/6 sash windows, returned cornice, centered circular windows in the gable ends, and slate gable roof all 20th century interpretations of Colonial style elements.

The Mt. Rainier United Methodist Church presently has a congregation of 180 members. It is opening its well maintained facility for use as a day care center and offices for local non-profit organizations, as a way to continue to serve its institutional function in the community.⁴

Notes

- 1 10th Anniversary Book, Mt. Rainier Methodist Episcopal Church, April 16, 1926. Available at the Church.
- 2 Land Records of Prince George's County, 138:114.
- 3 10th Anniversary Book.
- 4 Interview with Reverend Ralph L. Minker, Pastor, Mt. Rainier United Methodist Church, January 1987.

9. Major Bibliographical References

Survey No. P.C. #68-36

See Notes, #8

10. Geographical Data

Acreege of nominated property 26,374 square feet

Map 49 F-3

Quadrangle name Washington East D

Quadrangle scale _____

UTM References do NOT complete UTM references

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

C	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

D	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

E	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

F	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

G	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

H	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

11. Form Prepared By

name/title Marina King, Preservation Planner

organization Historic Preservation Commission date September 1987


street & number 14741 Gov. Oden Bowie Drive telephone 952-4609

city or town Upper Marlboro state MD

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438



Legend
 A - contributing 1-26 - inventory number
 E - noncontributing 3801 - address

WASHINGTON EAST



Chatham

University Hill
Creation Center

College Heights
Station

Northwestern
High Sch

Georges
Plaza

Grand
Jr High Sch

Chapel

Anacostia
River Park

Allison
Window

Wesley
St

Cottage

Byrd
Stadium

UNIVERSITY
OF MARYLAND

University
Park

Leland Memorial
Hospital

HYATTSVILLE

County
Government Bldg

Pumping
Sta

Peace
Cross

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Plainsboro

LAUREL
ST

Paine Branch
Park

COLLEGE PARK

College
Sch

BUILDING

College
Park Sch

WOODBURY ST

WOODBURY ST

SHANNON ST

Municipal
Bldg

W. Morgan
Memor

Northeast
P

Municipal
Bldg

Edmonston

BLUENAN

Blonsburg

High Sch

Shopping
Center

PG# 68-36



113
P.G. #68-36

Mt. Rainier United Methodist Church
Prince George's County, Maryland
Marina King
January 1987
Northeast elevation
Neg: Maryland Historical Trust
Annapolis, MD



NE
1000000

P.G. #68-36

Mt. Rainier United Methodist Church
Prince George's County, Maryland
Marina King
January 1987
Northeast elevation, Belltower
Neg: Maryland Historical Trust
Annapolis, MD



P.G. #68-36

Mt. Rainier United Methodist Church
Prince George's County, Maryland
Marina King
January 1987
Sanctuary, looking north
Neg: Maryland Historical Trust
Annapolis, MD



*Sanctuary
only - S*

P.G. #68-36

Mt. Rainier United Methodist Church
Prince George's County, Maryland
Marina King
January 1987
Sanctuary, looking south
Neg: Maryland Historical Trust
Annapolis, MD