

BELLEGROVE

AL-I-B-024 Bellegrove Weatherboard House
Rt. 40
Bellegrove, Allegany Co. MD
Not Eligible

This two story frame farmhouse has been demolished and replaced with a mobile home. It was not an outstanding example of its type and the site is not of any known archaeological significance. This site is recommended as not eligible for the National Register of Historic Places.

Prepared by Merry Stinson
Paula S. Reed and Associates, Inc.
105 N. Potomac St.
Hagerstown, MD 21740
301-739-2070

3/00

MARYLAND HISTORICAL TRUST	
Eligibility Recommended _____	Eligibility Not Recommended <input checked="" type="checkbox"/>
Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: _____	
Reviewer, OPS: <u><i>[Signature]</i></u>	Date: <u>6/1/2000</u>
Reviewer, NR Program: <u><i>[Signature]</i></u>	Date: <u>6/6/00</u>

2005

Bellegrove Weatherboard House
AL-1-B-024
Route 40
Bellegrove

This weatherboard house is located in the rural farming community of Bellegrove in eastern Allegany County. It is a typical farmhouse with its two stories and three bays wide frame structure. One unusual feature of this house is its low-set original windows on the front facade. The house is in poor condition but serves as a reminder of 19th century farming families in the eastern section of the county.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Bellegrove Weatherboard House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

south side Route 40

Sixth

CITY, TOWN

Bellegrove

___ VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

___DISTRICT

BUILDING(S)

___STRUCTURE

___SITE

___OBJECT

OWNERSHIP

___PUBLIC

PRIVATE

___BOTH

PUBLIC ACQUISITION

___IN PROCESS

___BEING CONSIDERED

STATUS

OCCUPIED

___UNOCCUPIED

___WORK IN PROGRESS

ACCESSIBLE

YES: RESTRICTED

___YES: UNRESTRICTED

___NO

PRESENT USE

___AGRICULTURE

___COMMERCIAL

___EDUCATIONAL

___ENTERTAINMENT

___GOVERNMENT

___INDUSTRIAL

___MILITARY

___MUSEUM

___PARK

PRIVATE RESIDENCE

___RELIGIOUS

___SCIENTIFIC

___TRANSPORTATION

___OTHER

4 OWNER OF PROPERTY

NAME

Earle Jewell

Telephone #:

STREET & NUMBER

Route 1 Box 32

CITY, TOWN

Little Orleans

___ VICINITY OF

Maryland 21766 STATE zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 470

Folio #: 735

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

Maryland 21502 STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

___FEDERAL ___STATE ___COUNTY ___LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

AL-I-B-024

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Bellegrove Weatherboard house is located on the southern side of Route 40 in Bellegrove.

The building consist of a two story, three bays wide frame structure with weatherboard. It rests on a low stone foundation of random rubble with a plain water table. The gable flank roof is covered with ribbed tin. Eaves consist of a cornic and fascia. Two original brick chimneys located inside end are in poor condition. A brick corbeled cap chimney is inside end on the addition.

The main entrance is in the center of the northern facade. It has a replaced four panel door. Windows are two over two lights pegged with wooden slipsills. A shed roofed wraparound veranda is on the north and west.

The weatherboard addition on the south rests on posts. Windows are six over six lights and two over two lights. A shed roofed porch is on the east.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

AL-I-B-024

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This weatherboard frame house is located in the eastern most section of Allegany County along Route 40. The area is very isolated and farming is the major industry of the area's residents.

One unusual feature of this house is its low set original windows on the front facade.

Although this house is in poor condition, it serves as a reminder of eastern Allegany County farmers and their way of life.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 25 Acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

David A. Dorsey, Historic Sites Coordinator
Shara Goodwin, Historic Sites Surveyor

ORGANIZATION

Allegheny County Historic Sites Survey

DATE
May 2, 1979

STREET & NUMBER

3 Pershing Street

TELEPHONE
777-5944

CITY OR TOWN

Cumberland

STATE
Maryland 21502

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO: AL-1-B-024

DATE: 9/2/78

REMODELING: Drastic, moderate, minor

NAME OF PROPERTY: Belle Grove Weatherboard

LOCATION OF PROPERTY: S SIDE Rt 40

DIRECTION DWELLING FACES: North

NAME OF OWNER: Earle L Jewell L 470 F 135 25.00 A

ADDRESS: Rt 1 Box 33
Little Orleans Md

STORIES: 1() 2() 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()

WINGS, ADDITIONS: on south on posts $\frac{6}{6} - \frac{2}{2}$ windows shed porch

DWELLING SHAPE: (square, cross, rectangular)

WALL CONSTRUCTION:

- FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
- BRICK: Bond type - common, English, Flemish. Sketch variants.
- STONE: Bond type - rubble, ashlar (random or regular), quoins-plain, rusticated
- LOG
- OTHER: Coverings

WALL FEATURES: Belt Course, Pilasters, Others cornerboards

FOUNDATIONS: High, Low, Brick, Stone RANDOM RUBBLE

WATER TABLE: None, Plain, Beveled, Moulded Brick
SLIPSLIPS

WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() other()
pegged() nailed() wide() narrow() mitred() pediment()

ENTRANCE, DOORS: LOCATION: center N Facade
HARDWARE: original() replaced()
FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
4 Paneled, Vertical, Horizontal Boards

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)
original() replaced() rafter ends, modillions, dentils, frieze, architrave

ROOF: Gable front, Gable flank, Hip, RIBBED Shed, Mansard, Gambrel, Flat, Dormers # _____
MATERIAL: wood shingles, slate, tin, asphalt; original() replaced()

PORCHES: SHAPE OF ROOF - shed() hip() gable() wrap around on N & W

CHIMNEYS: Number: 3 Brick() Stone() Corbeled(1) original(2) replaced(1)
Location: Flush end() Inside end() Outside end() Central() Interior()

ARCHES: Door & Windows: Keystone, Flat, Segmental, Semicircular

COMMENTS:

USE: _____
SIGNIFICANCE: _____



AL-1-B-024
BELLE GROVE WEATHERBOARD
RT 40 BELLE GROVE
USGS BELLE GROVE QUAD
1951



AL-1-B-024

BELLE GROVE WEATHERBOARD

US RT 40 BELLE GROVE

David A. Dorsey

9/2/78

southeast



AL-1-B-024

BELLE GROVE WEATHERBOARD

RT. 40 BELLE GROVE

David A. Dorsey

9/2/78

Northwest