

**MARYLAND HISTORICAL TRUST
NR-ELIGIBILITY REVIEW FORM**

NR Eligible: yes _____
no

Property Name: Wigfield Complex Inventory Number: AL-II-B-032

Address: Off of Wagner Road, 4 mi. north of route 51 City: Oldtown Zip Code: _____

County: Allegany USGS Topographic Map: Oldtown Quad

The Maryland Department of Natural Resources, Tawes State Office Bldg., 580 Taylor Avenue E-3, Annapolis, MD,
Owner: 21401

Tax Parcel Number: _____ Tax Map Number: _____ Tax Account ID Number: _____

Project: Razing request for Wigfield log structures Agency: Maryland Department of Natural Resources

Site visit by MHT Staff: no _____ yes _____ Name: _____ Date: _____

Eligibility recommended _____ Eligibility **not** recommended

Criteria: A B C D Considerations: A B C D E F G None

Is the property located within a historic district? no _____ yes _____ Name of district: _____

Is district listed? no yes Determined eligible? no yes District Inventory Number: _____

Documentation on the property/district is presented in:

Listing in the Maryland Inventory: A survey form was completed in 1976 by John Nelson, Joan Baldwin, and Steve Beale and another was completed by me in 2000.

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*

The Wigfield Complex consists of three structures: a mid-19th century log house and log barn ruin, as well as a frame shed dating from the early 20th century, that are located in a stream valley along a tributary of Town Creek.

The hand-hewn log house is two-stories tall, three-bays by one-bay wide, with V-notching and wood slab chinking. The log sills rest directly on the ground and these, along with many of the other logs, are deteriorating slowly; however a standing seam tin roof is still keeping water out of the structure. Over the past few decades it had been converted into a barn with hay storage on the second floor. The log barn ruin appears to have been only one-story tall, with construction details similar to the log house; but it is severely deteriorated and overgrown with vegetation. The frame shed is one-story tall with a corrugated tin roof, vertical wood siding, and circular sawn lumber.

These three structures exhibit utilitarian, log and frame construction characteristics common in Western Maryland, and do not meet the Criteria of the National Register. While they do not meet the standards of the National Register, the two log structures do represent examples of vernacular log construction from an early period of settlement in Oldtown, Maryland.

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended _____	Eligibility not recommended <input checked="" type="checkbox"/>
Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: _____	
_____ Reviewer, Office of Preservation Services	_____ Date
_____ Reviewer, NR program	_____ Date

✓-entered

200103576

Inventory Number: AL-II-B-032

Wigfield Complex

Allegany County, Maryland

C. Mazurek

3/20/00

Capsule Summary

The Wigfield Complex is located off of Wagner Road within Green Ridge State Forest in the vicinity of Oldtown, Maryland and includes three structures: a log house, a frame barn, and a log barn ruin. The log house is two stories tall and three bays by 1 bay wide with V-notching employed for the hand hewn logs attachment. The frame barn is not very old and is constructed of circular sawn lumber. The log barn has the V-notching attachment just like the house but it is now a ruin. This complex dates from the 1820's and was built by the Wigfield family who were early settlers of the area. These structures are now abandoned.

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Survey No. AL-II-B-032

1. Name of Property (indicate preferred name)

historic Wigfield Log House

other

2. Location

street & number Wagner Road, 4 miles north of route 51, Green Ridge State Forest not for publication

city, town Oldtown vicinity

county Allegany

3. Owner of Property (give names and mailing addresses of all owners)

name Maryland Department of Natural Resources

street & number Tawes State Office Building, 580 Taylor Avenue telephone (410) 260-8192

city, town Annapolis state and zip code Maryland 21401

4. Location of Legal Description

courthouse, registry of deeds, etc. Allegany County Courthouse tax map and parcel

city, town Cumberland liber and folio 453/1

5. Primary Location of Additional Data

- Individually Listed in the National Register/Maryland Register
 Contributing Resource in National Register District
 Contributing Resource in Local Historic District
 Determined Eligible for the National Register/Maryland Register
 Recorded by HABS/HAER
 HSR or Research report at MHT
 Other:

6. Classification

Category	Ownership	Current Function	Resource Count	
			Contributing	Noncontributing
<input type="checkbox"/> district	<input checked="" type="checkbox"/> public	<input type="checkbox"/> agriculture	<input type="checkbox"/> landscape	
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> commerce/trade	<input type="checkbox"/> recreation/ culture	3
<input type="checkbox"/> structure	<input type="checkbox"/> both		<input type="checkbox"/> religion	
<input type="checkbox"/> site		<input type="checkbox"/> defense	<input type="checkbox"/> social	
<input type="checkbox"/> object		<input type="checkbox"/> domestic	<input type="checkbox"/> transportation	3
		<input type="checkbox"/> education	<input type="checkbox"/> work in progress	
		<input type="checkbox"/> funerary	<input type="checkbox"/> unknown	
		<input type="checkbox"/> government	<input checked="" type="checkbox"/> vacant/not in use	
		<input type="checkbox"/> health care	<input type="checkbox"/> other:	
		<input type="checkbox"/> industry		
			Number of Contributing Resources previously listed in the Inventory _____	

7. Description

Survey No AL-II-B-032

Condition

excellent deteriorated
 good ruins
 fair altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The Wigfield structures are located in Allegany County within the vicinity of Oldtown, Maryland and are easily reached by taking Route 51 to Wagner road and then following the dirt road about four miles to the complex. The Wigfield log house is located on the left of Wagner road and is only about 10 feet from the shoulder of the road. This complex consists of 3 structures: the log house, a log barn ruin, and a wood frame barn; which are all located next to a small meandering stream.

The Wigfield log house is two stories tall and three bays by 1 bay wide, with approximate dimensions of 19 feet, by 25 feet. The plan consists of an open hall with one room on the downstairs and one room on the upstairs. There is no evidence of a chimney or later wood stove around which the house would be oriented, although the wood stove could have been removed. On the interior the access structure, stairway or ladder, to the second floor is missing.

Framing construction consists of hand hewn logs with a notching technique of V-notching employed for the assembly of these logs. The chinking between these logs consists of slabs of wood laid diagonally to form a very tight barrier to the elements, however to further insulate the spaces a mortar, which appears to be lime based, has been laid in between these slabs of wood. A tin roof is the present day covering, but this is an obvious replacement as the original roof was most likely wood shake. There is no basement or foundation, instead the logs rest directly on the ground.

The north elevation is a gable end and consists of one window on the first floor located directly under a window on the second floor. Window trim is minimal and crudely constructed, and the sashes have all been removed. In a previous inventory form completed in 1976 it was stated that the only remaining window contained 6/6 lights. The gable has wood siding laid vertically.

The east elevation is the front elevation and consists of two windows on the first floor with a door between them, and three windows located directly above these on the second floor. A porch extension which extends 10 feet out from the facade is not enclosed, but provides some protection from the elements. It is held up with log posts, however the flooring has deteriorated leaving just a dirt floor underneath. The porch roof forms a catslide roof as it extends from the main structure.

The south elevation is a gable end and has no windows or doors located on the facade. There are remnants of a simple vertical wood siding, that probably covered the entire structure, but was removed during a later period, probably when the structure was converted to the storage of hay. The pieces of siding that are left are circular sawn, and attached with modern nails, so they are most likely not the original sheathing.

The west elevation is the rear facade and contains on the first floor a doorway, a half window and a full window, in addition on the second floor there is a full window and a half window. Just as on the east elevation there is a deteriorated porch extension, which extends out 12 feet, however the a difference between the two is that this roof connection is dropped just below the main roof.

The frame barn is located approximately 25 feet to the west of the log house, with overall dimensions of 13 feet by 18 feet. The construction elements consist of vertical wood siding, a tin roof, and circular sawn lumber. A large doorway to the structure is located on the western facade of this structure, which is still in good condition.

The log barn located approximately 150 feet away, however is not in good a condition as the frame barn, due to the loss of the roof. Overall dimensions are 19 feet by 30 feet and just like the log house the logs on this barn have been constructed with V-notching. They are spaced closer together than the house and there is no evidence left of any sort of chinking used. Vertical siding covered the log structure, however most of this has deteriorated away. It appears as though the barn was only one story tall, however on the south elevation there is a remnant of a wooden ladder so the structure may have had a loft. The interior appears to have been only one room. There are various doors and windows on the structure that have been boarded up.

8. Significance

Survey No. AL-II-B-032

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input checked="" type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other:

Specific dates

Builder/Architect

Evaluation for:

National Register Maryland Register not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, and a narrative discussion of the history of the resource and its context. (For compliance reports, discuss evaluation on a DOE Form - see manual).

The Wigfield log house is significant for its architecture, which is log construction, as well as for its construction during the early settlement of the Oldtown area. Other surviving log houses in the area are the McLaughlin log house (AL-II-B-033) which dates from 1815, and the Hartsock log house (AL-II-B-031) which dates from the 1890's.

Log construction was common in Western Maryland due to the fact that it was inexpensive, the resources were plenty, and the construction was durable. "Log treatments utilized in the region fall into three groups: logs left in the round, logs hewn square or sawn, and thickly sawn planks" (Lanier and Herman). The Wigfield log house is not an example of the crudest form of log construction, with logs left in the round, nor is it the most finely constructed log construction, with logs sawn and planed into planks and then attached with wooden pins. Instead this construction falls somewhere in between with the logs sawn flat on the inner and outer faces and then the bark and natural roundness of the log left on the top and bottom sides where the chinking usually hides this unfinished detail. In addition the use of V-notching in the attachment of the timbers, an easily constructed type of joinery, suggests that this was not a high style log building, but rather a utilitarian log house.

According to the survey form completed by John Nelson, Joan Baldwin, and Steve Beale in 1976 the Wigfield log house dates from around 1820. They state that "in the 1800's, numerous log structures were built in Allegany county by the less wealthy inhabitants and that this house was reported to have been built by Mr. Wigfield a name that is found in the early settlement records of the Flintstone area".

At the time of the 1976 survey this land with the log house complex located on it was part of the E-V Sportsman Club which was owned by Anna S. Dixon. Since the last survey was completed this land transferred ownership to Christopher Coile who also used the land as hunting grounds. He in turn recently sold the land to the Maryland Department of Natural Resources for inclusion in Green Ridge State Forest.

These structures are now abandoned.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. AL-II-B-032

Name

Continuation Sheet

Number 8 Page 2

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE PRESERVATION PLAN DATA

Geographic Organization: Western Maryland

Chronological/Developmental Period(s): Agricultural-Industrial Transition

Prehistoric/Historic Period Theme(s): Architecture, Landscape Architecture, and Community Planning

Resource Type:

Category: Buildings

Historic Environment : Rural

Historic Function(s) and Use(s): Agriculture, Shelter

Known Design Source: Unknown

9. Major Bibliographical References

Survey No. AL-II-B-032

-
1. Lanier, Gabrielle and Herman, Bernard. Everyday Architecture of the Mid-Atlantic-Looking at Buildings and Landscapes. The Johns Hopkins University Press-Baltimore and London, 1997.
 2. Maryland Historical Trust Inventory Form completed by John Nelson, Joan Baldwin, and Steve Beale in 1976.

10. Geographical Data

Acreage of surveyed property _____

Quadrangle name Oldtown Quad

Quadrangle scale 1:24,000

Verbal boundary description and justification

The land, the E-V Sportsman Club, which was surveyed in 1976 included 369 acres, of which this has now been added to the Green Ridge State Forest holdings. The surveyed complex bounds Warfield Road, a feeder stream to Old Town Creek, and two open fields.

11. Form Prepared By

name/title Charlie Mazurek, Specialist in Historic Structures

organization MD Department of Natural Resources

date 3/20/00

street & number Tawes State Office Building, 580 Taylor Avenue

telephone (410) 260-8192

city or town Annapolis

state and zip code MD 21401

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
DHCD/DHCP
100 Community Place
Crownsville, MD 21032-2 023
410-514-7646

WIGFIELD LOG HOUSE, WAGNER ROAD, AL-II-B-032


ALLEGANY CO.

C. MAZUREK

3/7/00

3/16 SCALE

NORTH ↑




- • 2 STORIES TALL
- • LOG STRUCTURE
- • WOOD CHINKING
- • TIN ROOF (REPLACEMENT?)
- • 1 ROOM / 1 ROOM

DIRT FLOOR OPEN PORCH

WIGFIELD LOG HOUSE, WAGNER ROAD, AL-II-B-032
ALLEGANY CO.

C MAZUREK
3/7/00
NO SCALE
APPROX. MEASUREMENTS ONLY

← HIGHWAY



WIGFIELD LOG HOUSE, WAGNER ROAD, AL-II-B-032

ALLEGANY CO.


C. NAZUREK

3/7/00

3/16 SCALE

LOG BARN RUIN

- • NO ROOF
- • LOGS DETERIORATING
- • NO CHINKING LEFT
- • PREVIOUSLY USED AS LIVESTOCK BARN



B-068

AI-II-B-032
Wigfield Log House
Wagner Rd.
USGS - Oldtown Quad
1:24,000
1950

AI-II-B-033

2 STORY Log MANSE

AI-II-B-032

AI-II-B-031


CA 1846
2 STORY

AI-II-B-029

AI-II-B-037

AI-II-I

AI-II-E





AL-11-B-32

Wigfieldy Co's HOUSE

AnneArundel Co. MD

C. MAZUREK

3/2003

MD Dept OF NATURAL RESOURCES

Co's House, NORTH FACADE

1 OF 6



A-11-B-32

WISCONSIN LOG HOUSE

Allegheny Co., MD

C. MAZUREK

3/2000

MD Dept. of Natural Resources

Log Cabin, SE Falls

2000



A-11-B-32

WIGFIELD LOG HOUSE

ALLEGANY CO., MD

C. MAZURK

3/2000

MD Dept. OF NATURAL RESOURCES

LOG HOUSE, NORTH FACADE

3 of 6



AL-1-B-32

WINGFIELD LAY - OISE

ALBERTA CO. MD

C MAZUREK

3/2000

MD DEPT. OF NATURAL RESOURCES

FISH & BIRD, 1. EAST

4 OF 5



AL-11-B-32

Wigfield Log House

Allegheny Co., PA

C. MAZUREK

3/2010

MD Dept. OF NATURAL RESOURCES

Log House; SE F-10-1105

5 OF 6



AL-11-8-33

Wigfield Log House

Allegheny Co., Pa.

C. Mazurke

3/2000

MD Dept. of NATURAL RESOURCES

NORTH FACADE, OF LOG HOUSE

0 50 0

WIGFIELD LOG HOUSE

AL-II-B-032

4.8 miles north of Route 51 on Wagner Rd.
ca. 1820

The Wigfield Log House represents one of Allegany County's older log structures that has been left to deteriorate. Hewn logs compose the walls, which rest directly on the ground. Dovetail notching was used to pin the corners together on the house. Windows and doors have been removed to facilitate the present usage as a cattle shelter.

MARYLAND HISTORICAL TRUST

0101695306
AL-II-B-032

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Wigfield Log House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

4.8 miles north of Rt. 51 on Wagner Road

CITY, TOWN

Oldtown

VICINITY OF

CONGRESSIONAL DISTRICT

Sixth

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH

PUBLIC ACQUISITION

- IN PROCESS
- BEING CONSIDERED

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

ACCESSIBLE

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER

4 OWNER OF PROPERTY

NAME

Anna S. Dixon

Telephone #: 395-5148

STREET & NUMBER

P.O. Wagner Rd.

CITY, TOWN

Oldtown

VICINITY OF

STATE, zip code
Maryland 21555

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 453

Folio #: 1

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland,

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Wigfield Log House is located 4.8 miles north of Route 51, on the east side of the Wagner Road.

The Wigfield Log House is a two story, three bay wide log structure. The logs are hewn and are cornered with dove tail notches. Joists are exposed between the 1st and 2nd story. The whole structure is built directly on the ground with no foundation. All windows, with the exception of one containing 6 over 6 lights, have been removed, and the doors are gone. A gabled roof covers this rectangular structure, and now has a replaced tin covering. Shed roofs supported by wooden beams have been added to the front and rear of the house; the present usage is hay storage. The structure has been allowed to deteriorate, but was very sound for many years.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES CA. 1820 BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Wigfield Log House was built circa 1820 as a simple shelter for a subsistence type of farm. The log structure was a popular form of housing in the early settlement ~~time~~ period. The facade was inexpensive to build, easy to construct and extremely sturdy. In the early 1800's, numerous log structures were built in the county by the less wealthy inhabitants. Years after their construction, many of these buildings were covered with a variety of sidings; however, on this particular structure, the logs have been left exposed.

The house is reported to have been built by Mr. Wigfield, a name that is found in the early settlement records of the Flintstone area. The house is badly deteriorated and is presently used as a live stock shelter.¹

1 Interview with John L. Carder, September 22, 1976

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Cumberland, Maryland

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 369 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

John Nelson, Joan Baldwin & Steve Beale

ORGANIZATION

Allegany County Historical Sites Survey

DATE

10/11/76

STREET & NUMBER

507 National Highway

TELEPHONE

777-8991

CITY OR TOWN

LaVale, Maryland

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO. AL-II-B-032

453-1

DATE: 9/22/76

369 Acres

REMODELING: Drastic, moderate, minor

Clarence

NAME OF PROPERTY: Wigfield Log House

Deryl Henry 395-550

LOCATION OF PROPERTY: 4.8 miles North of 51 on Wagner Road

DIRECTION DWELLING FACES: West 395-5148

NAME OF OWNER: E-V. Sportsman Club (Anna S. Dixon)

ADDRESS: Wagner Rd P.O.

Oldtown MD. 21555

STORIES: 1() 2() 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()

WINGS, ADDITIONS:

Dwelling Shape: (square, cross, rectangular)

WALL CONSTRUCTION:

- () FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
- () BRICK: Bond type- common, English, Flemish. Sketch variants.
- () STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
- () LOG
- () Other: Coverings

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS Plain

FOUNDATIONS: HIGH, LOW, BRICK, STONE Built on Ground

WATER TABLE: NONE, PLAIN, BEVELED, MOUNDED BRICK

WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() other()
Most are Gone pegged () nailed () wide () narrow () mitred () pediment ()

ENTRANCE, DOORS: LOCATION: Gone
HARDWARE: original() replaced()
FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
Paneled, Verticle, Horizontal Boards

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)
original() replaced() Rafter Ends, Modillions, Dentils, Frieze, Architrave

ROOF: GABLE FRONT, GABLE FLANK, HIP, SHED, MANSARD, GAMBREL, FLAT, DORMERS #
MATERIAL: wood shingles, slate, tin asphalt original() replaced()


PORCHES: SHAPE OF ROOF - shed() hip() gable() 2, Front & Rear with tin roof

CHIMNEYS: NUMBER _____ BRICK() STONE() CORBELLED() original() replaced()
LOCATION: Flush end() Inside end() Outside end() Central() Interior()

ARCHES: Door and window: Keystone, Flat, Segmental, Semicircular

COMMENTS:

Use - Hay Storage
Significance - Arch
Date Constructed - circa 1820
Condition - Deteriorated



● AI-II-B-033

● AI-II-B-068

AI-II-B-030
Wigfield Log House
Wagner Rd.
USGS - Oldtown Quad
24,000
1960

● AI-II-B-032

● AI-II-B-031

● AI-II-B-

● AI-II-B-029

● AI-II-B-037

● AI-II-B-



AL-11-B-032

Winfield Log House

4.8 miles N. of Rt. 51 on Wagner Rd.

John Nelson

9/22/76

WST



Wigfield Log House

AK-II-B-032


4.8 miles North of Rt. 51 on

Wagner Road

John Nelson

9/22/76

North east



Wigfield Log House (Barn)

AL-II-B-032

4.8 miles North of Rt. 51 on

Wagner Road

John Nelson

9/22/76

Northeast