

Davis Log House
AL-III-B-145
Collier's Run Road
Near Spring Gap

Davis Log House was moved from up the hollow to its present location. The original log structure is one and a half stories tall and two bays wide and is now covered with insul brick. The frame addition abutting the log house was built ca. 1910 and is frame with insul brick. Although the house does not retain its original appearance, this house is typical of many others in eastern Allegany County.

MARYLAND HISTORICAL TRUST

0107315904

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Davis Log House

2 LOCATION

STREET & NUMBER

Collier's Run Road

Sixth

CITY, TOWN

Spring Gap

 VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

 DISTRICT BUILDING(S) STRUCTURE SITE OBJECT

OWNERSHIP

 PUBLIC PRIVATE BOTH

PUBLIC ACQUISITION

 IN PROCESS BEING CONSIDERED

STATUS

 OCCUPIED UNOCCUPIED WORK IN PROGRESS

ACCESSIBLE

 YES: RESTRICTED YES: UNRESTRICTED NO

PRESENT USE

 AGRICULTURE COMMERCIAL EDUCATIONAL ENTERTAINMENT GOVERNMENT INDUSTRIAL MILITARY MUSEUM PARK PRIVATE RESIDENCE RELIGIOUS SCIENTIFIC TRANSPORTATION OTHER**4 OWNER OF PROPERTY**

NAME

Mark M. Davis

Telephone #: 724-4733

STREET & NUMBER

Route 4

CITY, TOWN

Cumberland

 VICINITY OF

STATE, zip code

Maryland 21502

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 194

Folio #: 108

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

 FEDERAL STATE COUNTY LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

AL-III-B-145

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input checked="" type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Davis Log House stands on the western side of Collier's Run Road near Spring Gap.

This house originally consisted of a small log house one and one half stories tall and two bays wide. Wall construction is of log with a covering of insul brick. It rests on stones placed at the corners. The gable flank roof is covered with tar paper. Eaves consist of close verges on the gable end and rafter ends on the flanks. The offset entrance is made of vertical boards. Six over six light windows are pegged. A shed roofed porch has plain wooden posts. A shed addition with an outside end cinderblock chimney is on the northwest.

A large addition abutting the southwest of the original is frame with insul brick. The foundation is low of random rubble with a plain water table. The gable flank roof is covered with asphalt shingles. Eaves consist of a box cornice and soffit with returns. A brick chimney is in the center of this addition. Windows arepegged one over one light, with wooden lugsills, some with pediments. A hip roofed porch has decoratively cut and bracketed posts.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

AL-III-B-145

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This house is located in the Spring Gap region of Allegany County, a distinctly rural and agricultural community. There are no other major industries in this area of the county to support the population, so farming has long been the main occupation of Spring Gap area residents. Over 85% of the County's population lived on farms well into the 19th century. (1)

(2) The Davis Log House was moved to its present location from up the hollow. The structure was originally one and a half stories tall and two bays wide. The frame addition abutting the original log house was built circa 1910. (3)

Although it does not retain its original appearance, this house typifies many others in eastern Allegany County.

- (1) Harry I Stegmaier, Jr. et. al. Allegany County, A History (Parsons, W.Va.: McClain Printing Company), p. 97
- (2) Interview with Mr. Davis, resident, 9/12/78.
- (3) Ibid

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Stegmaier, Harry Jr. et. al. Allegany County, A History. Parsons, West Va.: McClain Printing Company, 1976.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE David A. Dorsey, Historic Sites Coordinator
Shara Goodwin, Historic Sites Surveyor

ORGANIZATION Allegany County Historic Sites Survey DATE 4/19/79

STREET & NUMBER 3 Pershing Street, County Office Building TELEPHONE 777-5944

CITY OR TOWN Cumberland, STATE Maryland 21502

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO: 46

DATE: 9/12

REMODELING: Drastic, moderate, minor

no title search

NAME OF PROPERTY: DAVIS LOG HOUSE

LOCATION OF PROPERTY: Collier Run Rd AL-III-B-145

DIRECTION DWELLING FACES: SW

NAME OF OWNER: ca 1910

ADDRESS: Frame ca 1910 ORIGINAL LOG - moved from up hall

TAYLOR ST May 1910 Davis INH - EST 9210 parcel 18 ph. #

STORIES: 1() 2() 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()

WINGS, ADDITIONS: on NE - gabled on posts faced SE

DWELLING SHAPE: (square, cross, rectangular) stones on corners.

WALL CONSTRUCTION:

- FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
- BRICK: Bond type - common, English, Flemish. Sketch variants.
- STONE: Bond type - rubble, ashlar (random or regular), quoins-plain, rusticated
- LOG
- OTHER: Coverings insul

WALL FEATURES: Belt Course, Pilasters, Others _____

FOUNDATIONS: High, Low, Brick, Stone rubble on frame

WATER TABLE: None, Plain, Beveled, Moulded Brick

WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() other()
pegged() nailed() wide() narrow() mitred() pediment() wood log

ENTRANCE, DOORS: LOCATION: offset SW ← w/ fluted trim
HARDWARE: original() replaced()
FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
Paneled, Vertical, Horizontal Boards

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed) returns on frame
original() replaced() rafter ends, modillions, dentils, frieze, architrave

ROOF: Gable front, Gable flank, Hip, Shed, Mansard, Gambrel, Flat, Dormers #
FRAM MATERIAL: wood shingles, slate, tin, asphalt; asphalt on both original() replaced()

PORCHES: SHAPE OF ROOF - shed() hip() gable() 1 concrete block outside add.

CHIMNEYS: Number: 2 Brick() Stone() Corbeled() original() replaced()
Location: Flush end() Inside end() Outside end() Central() Interior() of frame

ARCHES: Door & Windows: Keystone, Flat, Segmental, Semicircular

COMMENTS: 2/2 log is gabled - 2 Bays one upper window in gable overhang

USE: _____
SIGNIFICANCE: _____
DATE CONSTRUCTED: _____
CONDITION: _____


WILEY FORD 6.2 MI.
3 MI. TO W. VA. 28
(CREAPTOWN) 5263 III/SE

4381

4380

32'30"

4379





AZ-111-B-145

DAVIS LOG HOUSE

COLLIERS RUN RD. SPRING GAP

David A. Dossy

8/12/78

EAST



AL-111-B 145

DAVIS LOG HOUSE

COLLIER'S RUN RD Spring Gap

David A. Dotsey

9/12/78

West