

AL-VI-B-243

Clise Farm

Miller

Private

Circa 1900

The Clise Farm was built shortly after the turn of the century by members of the Clise family. (interview) The two story, three bay by two bay farmhouse is typical of dwellings built early in the twentieth century in western Maryland. In addition to the farmhouse, several original outbuildings remain intact. These include a milkhouse, a sawmill, a spirnghouse, and a drive-in corncrib.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Clise Farm

2 LOCATION

STREET & NUMBER

South of Route 55

CITY, TOWN

Miller

___ VICINITY OF

CONGRESSIONAL DISTRICT

6th

STATE

Maryland

COUNTY

Allegany County

3 CLASSIFICATION

CATEGORY

___DISTRICT

BUILDING(S)

___STRUCTURE

___SITE

___OBJECT

OWNERSHIP

___PUBLIC

PRIVATE

___BOTH

PUBLIC ACQUISITION

___IN PROCESS

___BEING CONSIDERED

STATUS

OCCUPIED

___UNOCCUPIED

___WORK IN PROGRESS

ACCESSIBLE

___YES RESTRICTED

___YES UNRESTRICTED

NO

PRESENT USE

AGRICULTURE

___COMMERCIAL

___EDUCATIONAL

___ENTERTAINMENT

___GOVERNMENT

___INDUSTRIAL

___MILITARY

___MUSEUM

___PARK

PRIVATE RESIDENCE

___RELIGIOUS

___SCIENTIFIC

___TRANSPORTATION

___OTHER

4 OWNER OF PROPERTY

NAME

John Clise

Telephone #:

STREET & NUMBER

CITY, TOWN

___ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE

Maryland 21502

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

None

DATE

___FEDERAL ___STATE ___COUNTY ___LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE		CHECK ONE	
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE	<input type="checkbox"/> MOVED	DATE _____
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED			
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED				

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Clise Farm is located south of Route 55 at Miller. The farm consists of a farmhouse and ten outbuildings. The farmhouse is two stories tall, three bays wide on the facade (NW elevation), and one bay deep. The house is "T" shaped due to the addition of a two story frame wing to the southeastern elevation which is two bays wide and one bay deep. The frame farmhouse has walls of tongue and groove flush boards covered with asbestos shingle siding. It rests on a high rubble stone foundation. The gabled roofs of both the main block and the addition are covered with asphalt shingles.

A porch on the facade has a hipped roof supported by capped square wooden posts. A two tiered porch on the northeastern elevation of the addition has a shed roof supported by square wooden posts. Windows are pegged 6/6 sash. An entrance in the center of the facade has a one light transom and an original door. The door has two horizontal panels and two square panels surmounted by one pane of frosted glass with an urn design. Engraved hardware of the door is original. A central chimney on the main block and an end chimney on the addition are of brick.

A springhouse is located immediately to the southwest of the farmhouse. The two buildings are connected by a small frame addition with a gabled roof. The frame springhouse is one story tall and is covered with german siding and insul brick siding. It rests on a high random ashlar stone foundation and has a gabled roof. A spring which emerges from beneath a stone retaining wall to the southeast of the springhouse flows through the foundation of the structure.

A small frame milking house, a pavillion-like sawmill, and a recently rebuilt shop which rests on a highstone foundation are located to the northwest of the farmhouse. Two frame granaries, a drive-in, double bin corn crib, two shed roofed board and batten cow sheds, a rebuilt barn, and the foundation of a silo are located to the north of the farmhouse.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES ca. 1900

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Clise Farm was built shortly after the turn of the century by members of the Clise family. (interview) The two story, three bay by two bay farmhouse is typical of dwellings built early in the twentieth century in western Maryland. In addition to the farmhouse, several original outbuildings remain intact. These include a milkhouse, a sawmill, a springhouse, and a drive in corncrib.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Interview with Mr. John Clise, 7/16/81.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

David A. Dorsey, Historic Sites Surveyor

ORGANIZATION

Maryland Historical Trust/Bureau of Mines

DATE

October 1981

STREET & NUMBER

21 State Circle, Shaw House

TELEPHONE

(301) 269-2438

CITY OR TOWN

Annapolis


STATE

Maryland 21401

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



Lonaconing, MD-WV
USGS 7.5 Minute Series
Scale 1:24,000
1950; photorevised 1974

AL-VI-B-243
Clise Farm
South of Route 55
Miller



AL-VI-B-243
Clise Farm
Allegany Co., MD
David A. Dorsey 7/81
Farmhs. NW elevation



AL-VI-B-243

Clise Farm

Allegany Co., MD

David A. Dorsey 7/81

Springs. NW elev.



AL-VI-B-243

Clise Farm

Allegany Co., MD

David A. Dorsey 7/81

Outbldgs. View to the SW



AL-VI-B-243
Clise Farm
Allegany Co., MD
David A. Dorsey 7/81
Outbldgs, View to the S



AL-VI-B-243

Clise Farm

Allegany Co., MD

David A. Dorsey 7/81

Corncrib, NW elev.