

Duckworth Farmhouse
AL-V1-C-200

This farmhouse, built during the last quarter of the nineteenth century, was the home of Alton C. Duckworth. A deed of 1886 by which Duckworth donated land for a schoolhouse near the farmhouse identified the building as Duckworth's residence.

The large building is in original condition. It is a two story, five bays wide frame structure with german siding. A slate roof was covered with tar paper; the eaves are bracketed. Pegged six over six light sash windows and the main entrance are in original condition. The entrance, with sidelights and a four light transom, included a wide door has four moulded panels, the upper two with semicircular tops, and original hardware. A two tiered porch on either side of the "L" shaped southwestern facade has decoratively bracketed posts.

Although in deteriorated condition, the Duckworth farmhouse is a physical reminder of the cultural awareness of rural residents of Allegany County during the nineteenth century.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Duckworth Farmhouse

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Stoney Run Road

Sixth

CITY, TOWN

Westernport

 VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input checked="" type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE
<input type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> MUSEUM
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> COMMERCIAL
<input type="checkbox"/> SITE	<input type="checkbox"/> PUBLIC ACQUISITION	<input type="checkbox"/> ACCESSIBLE	<input type="checkbox"/> PARK
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> EDUCATIONAL
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> ENTERTAINMENT
		<input type="checkbox"/> NO	<input type="checkbox"/> GOVERNMENT
			<input type="checkbox"/> INDUSTRIAL
			<input type="checkbox"/> MILITARY
			<input type="checkbox"/> PRIVATE RESIDENCE
			<input type="checkbox"/> RELIGIOUS
			<input type="checkbox"/> SCIENTIFIC
			<input type="checkbox"/> TRANSPORTATION
			<input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

Edwin W. Michael

Telephone #: 463-2207

STREET & NUMBER

Route 1

CITY, TOWN

Barton

VICINITY OF

STATE Maryland 21528 code

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 225

Folio #: 315

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE Maryland 21502

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

 FEDERAL STATE COUNTY LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

AL-11-000

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farmhouse consists of a two story, five bays wide "L" shaped frame structure with german siding. It rests on a high foundation of random ashlar stone with a plain water table. The gable flank roof is of slate covered with tar paper. Eaves consist of a cornice, soffit, and frieze with simple brackets. Two chimneys located inside end and one on the interior are of brick with stone caps.

The main entrance in the center of the northwestern facade includes a four light transom, sidelights of three lights and one moulded panel each, and a wide door with two semicircular arched and two rectangular moulded panels and original hardware. Windows are wide, pegged six over six lights with wooden lugsills. A two tiered veranda runs the length of the southeastern and southwestern facades. It rests on tall wooden posts with lattice work. The shed porch roof is supported by square wooden posts with decorative brackets and a plain balustrade.

A hipped slate porch roof on the northwest is supported by tapered wooden roman doric columns. Two barns, one a dairy barn, on the property are indeteriorating condition.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farmhouse, built during the last quarter of the nineteenth century, was the home of Alton C. Duckworth. A deed of 1886 by which Duckworth donated land for a schoolhouse near the farmhouse identifies the building as Duckworth's residence. (1)

The large building is in original condition. It is a two story, five bays wide frame structure with german siding. A slate roof was covered with tar paper; the eaves are bracketed. Pegged six over six light sash windows and the main entrance are in original condition. The entrance, with sidelights and a four light transom, includes a wide door has four moulded panels, the upper two with semicircular tops, and original hardware. A two tiered porch on either side of the "L" shaped southeastern facade has decoratively bracketed posts.

Although in deteriorated condition, the Duckworth farmhouse is a physical reminder of the cultural awareness of rural residents of Allegany County during the nineteenth century.

(1) Allegany County Land Records, Liber 63, Folio 208

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 123.4 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE

David A. Dorsey, Historic Sites Coordinator

ORGANIZATION

Allegany County Historic Sites

DATE

August 24, 1979

STREET & NUMBER

3 Pershing Street

TELEPHONE

777-5944

CITY OR TOWN

Cumberland,

STATE

Maryland 21502

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO: A2-VI-C-200

DATE: 10/31/79

REMODELING: Drastic, moderate, minor

NAME OF PROPERTY: Duckworth Farmhouse

LOCATION OF PROPERTY: Stray RunRD near Westempot

DIRECTION DWELLING FACES: NW

NAME OF OWNER: Edwin W. Michael Rt. 1 Burton 463-2207

ADDRESS: _____

STORIES: 1() 2() 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()

WINGS, ADDITIONS:

DWELLING SHAPE: (square, cross, rectangular) L

WALL CONSTRUCTION: german siding

- FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
- BRICK: Bond type - common, English, Flemish. Sketch variants.
- STONE: Bond type - rubble, ashlar (random or regular), quoins-plain, rusticated
- LOG
- OTHER: Coverings

WALL FEATURES: Belt Course, Pilasters, Others _____

FOUNDATIONS: High, Low, Brick, Stone random ashlar

WATER TABLE: None, Plain, Beveled, Moulded Brick

WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() other() wooden logsills
pegged() nailed() wide() narrow() mitred() pediment()

ENTRANCE, DOORS: LOCATION: center NW sidelights each of slights 1 panel
HARDWARE: original() replaced() 4 light transoms
FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
Paneled, Vertical, Horizontal Boards 2 semicircular arched panes
2 rectangular

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)
original() replaced() rafter ends, modillions, dentils, frieze, architrave
SIMPLE BRACKETS

ROOF: Gable front, Gable flank, Hip, Shed, Mansard, Gambrel, Flat, Dormers # _____
MATERIAL: wood shingles, slate, tin, asphalt; original() replaced()

PORCHES: SHAPE OF ROOF - shed() hip() gable()
SE SW NW TWO TIERED veranda Plain Balustrade

CHIMNEYS: Number: 3 Brick() Stone() Corbeled() STONE CAPS original() replaced()
Location: Flush end() Inside end(2) Outside end() Central() Interior(1)

ARCHES: Door & Windows: Keystone, Flat, Segmental, Semicircular


COMMENTS:

USE: farm
SIGNIFICANCE: architecture agr.
DATE CONSTRUCTED: _____
CONDITION: deteriorated

(veranda) shed roof w/ deco. brackets,
supported by wooden posts w/
lattice.
hipped roof NW slate w/ tapered
Roman Doric Columns



WESTERNPORT 1.2 MI.
PIEDMONT, W. VA. 1.6 MI.



VERTICAL MAP ACCURACY STANDARDS
SURVEY, WASHINGTON, D. C. 20242
AND SYMBOLS IS AVAILABLE ON REQUEST



AL-VI-C-200
DUCKWORTH FARMHOUSE
STONEY RUN WESTERNPORT
0565 BARTON QUAD

ROAD CLASSIFICATION
1964
Medium-duty ——— Light-duty ———
Unimproved dirt - - - - -
○ State Route

BARTON, MD.
N3930-W7900, 7.5

1947
AMS 5163 II SE—SERIES V833

(KEYSER)
5262 IV NW

AI-VI



AL-VI-C-200

DUCKWORTH FARMHOUSE
STONEY RUN, WESTERNPORT

DAVID A. DORSEY

10/31/78

SOUTH



A2-VI-C-200
DUCK WORTH FARMHOUSE
STONEY RUN, WESTERNPORT
DAVID A. DORSEY

10/31/78

North



AI-VI-C-200
DUCKWORTH FARMHOUSE
STONEY RUN, WESTERNPORT
DAVID A. DORSEY

10/31/78

DETAIL - ENTRANCE
N.W. FACADE