

AI - VII - A - 022
Ritter and Watts Inn
Frostburg

1843

In 1843 the Ritter and Watts Inn in Frostburg was established as a very practical style of hostelry and provided accommodation for travelers of the nearby National Road. The foundation is constructed of stone and supports an "L" shaped frame structure, which has been covered with asbestos shingles and is two stories high and six bays wide including the side wing. The facade features one-over-one light windows and is covered by a replaced asphalt shingle, gabled roof.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Ritter & Watts Inn

AND/OR COMMON

Rowe Apartments

2 LOCATION

STREET & NUMBER

61,63 Broadway

CITY, TOWN

Frostburg

VICINITY OF

CONGRESSIONAL DISTRICT

Sixth

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input checked="" type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

Ronald Rowe

Telephone #: 689-3613

STREET & NUMBER

41 Linden Street

CITY, TOWN

Frostburg

VICINITY OF

STATE, zip code

Maryland 21532

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 472

Folio #: 737

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Ritter Watts Inn is located at 61, 63 Broadway in Frostburg, Allegany County on the northwest side of the street at the intersection of Frost Avenue.

The former inn basically consists of a two story, six bays wide "L" shaped structure, a central block with one wing. The building is a frame structure with plain wall features and covered with replaced asbestos siding. The facade is supported by a low stone foundation without a water table. The roof of the principal facade is gabled and is covered by replaced asphalt shingles as well as the gable roof of the wing forming the "L" of the structure. Windows in the structure all feature double hung wooden sash frames with one-over-one lights and plain trim. Windows on the principal facade feature a pediment, and the front face of this main block exhibit windows grouped in twos and are evenly divided across the facade. The main entrances are located on the front southeast face of the structure. One entrance opens to the main facade; the other to the wing, and both display a transom and transom light. The entrances are covered by a three bay end porch with hip roof supported by cushion columns and brick supports and the porch is banistered. In the front gable is found a small gothic sash window with one-over-one lights. One corbeled brick chimney is located on the end of the wing and appears to be original.

The building appears structurally sound but alterations have been made on the interior when renovated for apartments.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input checked="" type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES Mid 19th century 1843 BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The old Ritter and Watts Inn is a mid nineteenth century hostelry which offered the traveler lodging and board for overnight accommodations. The building is representative of the utilitarian type of architecture with little decoration that was used for less fashionable hotels. A useful structure in its day, the building has been converted for apartments by the present owner and the exterior is in need of repair. It would certainly enhance the beauty of the structure and the architectural heritage of Frostburg if the exterior of the building was restored to original appearance.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Cumberland, Maryland

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 63.6' x 63'

VERBAL BOUNDARY DESCRIPTION

61, 63 Broadway

Boundary Lines Southeast & Northwest 63' Lines South West & Northeast 63.6'

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

John E. Nelson, Program Coordinator of All. Co. Historic Sites

ORGANIZATION

Allegany County Historic Sites Survey

DATE

4/21/76

STREET & NUMBER

10 Park Lane

TELEPHONE

689-8486

CITY OR TOWN

Frostburg

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO. A1-011-A-022

Liber-472
Folio-737

DATE: 4/15/76

63.6' x 63'

REMODELING: Drastic, moderate, minor - Interior - Now Apartments

NAME OF PROPERTY: Ritter and Watts Inn

LOCATION OF PROPERTY: 61-63 Broadway

DIRECTION DWELLING FACES: Southeast

NAME OF OWNER: Ronald Rowe

ADDRESS: 41 Linden St
Frostburg, MD. 21532

STORIES: 1() 2() 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()

WINGS, ADDITIONS: Porch Addition

Dwelling Shape: (square, cross, rectangular) - Central Block - one wing

WALL CONSTRUCTION:
Asbestos Siding
 FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
 BRICK: Bond type- common, English, Flemish. Sketch variants.
 STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
 LOG
 Other: Coverings Siding - Asbestos

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS Plain

FOUNDATIONS: HIGH, LOW BRICK, STONE

WATER TABLE: NONE, PLAIN, BEVELED, MOULDED BRICK

WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() other()
Plain Trim pegged () nailed () wide () narrow () mitred () pediment ()

ENTRANCE, DOORS: LOCATION: Southeast
HARDWARE: original() replaced()
PAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
Paneled, Verticle, Horizontal Boards With Verticle Window

CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)
original() replaced() Rafter Ends, Modillions, Dentils, Frieze, Architrave

ROOF: GABLE FRONT, GABLE FLANK, HIP, SHED, LANSARD, GENERAL, FLAT, FORMERS #
MATERIAL: wood shingles, slate, tin, asphalt original() replaced()

PORCHES: SHAPE OF ROOF - shed() hip() gable() 3 Bay End Porch - Cushion Columns

CHIMNEYS: NUMBER 1 BRICK() STONE() CORBELLED() original() replaced()
LOCATION: Flush end() Inside end() Outside end() Central() Interior()

ARCHES: Door and window: Keystone, Flat Segmental, Semicircular

COMMENTS:
Use - Apartments
Significance - Arch
Date Constructed - 1843
Condition - Fair

Key points regarding interior architecture.

*Interior Remodeled
for apartments*

1. Floor plan

No through hall--How many rooms long and deep?
Where is stairway? Straight or winding?

With through hall--Rooms on both sides? How many?
Rooms on one side only? How many?
Is stair in through hall?
Open or enclosed? Straight--one run. Straight--landing
How many? Curved.
If not in hall, where is stair?

2. Wall finish: plaster, paneled, board partition
Note presence of chair rail, cornice, etc.

3. Fireplaces: How many? Parallel to walls or diagonal in corner?
Mantels: wood--mouldings, pilasters, columns
masonry--marble(what color?), brick


3. Doors: on the inside of exterior doors, note the presence of applied flush boards and their direction (diagonal, vertical, horizontal). In general are doors paneled or ledge or other?

4. Door and window trim: plain, architrave; fluted, reeded; pilasters

5. Kitchen: Where is original if extant or known (marked by very large fireplace)? Separate building; wing to principal dwelling; within principal dwelling? On which floor of any of the above?

6. Note presence of wood (if any) on any wooden member removed.

481



AI-VII-A-034

AI-VII-A-033

AI-VII-A-012

AI-VII-A-036

AI-VII-A-035

AI-VII-A-032

AI-VII-A-009

AI-VII-A-008

AI-VII-A-005

AI-VII-A-010

AI-VII-A-004

AI-VII-A-006

AI-VII-A-011

AI-VII-A-019

AI-VII-A-015

AI-VII-A-013

AI-VII-A-001

AI-VII-A-016

AI-VII-A-014

AI-VII-A-031

AI-VII-A-018

AI-VII-A-017

AI-VII-A-028

AI-VII-A-020

AI-VII-A-026

AI-VII-A-027

AI-VII-A-021

AI-VII-A-023

AI-VII-A-022

AI-VII-A-025

AI-VII-A-024

AI-VII-A-002

AI-VII-A-003

AI-VII-A-029

AI-VII-A-025
Ritter Watts Inn
63 Broadway

FROST VILLAGE

Frostburg City Map
1" = 500'



Ritter Watts Inn

A1-VII-A-022

61-63 Broadway Frostburg

John E. Nelson

4/15/76

North



Ritter Watts Inn

A1-V11-A-022

61-63 Broadway Frostburg

John E. Nelson

4/15/76

West