

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 1161</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>Apartments</u>
ORIGINAL USE: <u>Residence</u>
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()
THEME:
STYLE: <u>Four Square</u>
DATE BUILT: <u>c.1910</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>147 Prince George Street</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map32 Par 536</u>
OWNER: <u>Sharyn G. Fuller</u>
ADDRESS: <u>147 Prince George Street</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (✓) State () National () <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone () Brick (X) Concrete () Concrete Block ()
2. Wall Structure
 - A. Wood Frame: Post and Beam () Balloon (X)
 - B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other:
3. Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
 Novelty () Stucco (X) Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer () Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Other:
4. Roof Structure
 - A. Truss: Wood (X) Iron () Steel () Concrete ()
 - B. Other:
5. Roof Covering: Slate (X) Wood Shingle () Asphalt Shingle () Sheet Metal ()
 Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers () Cupolas () Dormers (X) Chimneys (X) Sheds () Ells ()
 Wings () Other:

Roof Style: Gable () Hip (X) Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 2 1/2
 Number of Bays: 3 x 3
 Approximate Dimensions: 25 x 40

Entrance Location: Center at porch

THREAT TO STRUCTURE:
 No Threat (X) Zoning () Roads ()
 Development () Deterioration ()
 Alteration () Other:

LOCAL ATTITUDES:
 Positive () Negative ()
 Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Hipped dormer, boxed cornice, slate hipped roof; second floor windows double at outer bay, tripled at first floor; full width porch continues across contiguous structure, with tapered square posts, stucco infill below rail.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

One half of a double Four-Square style residence, altered by stucco facades but still contributing to streetscape. Only structures in block set back from sidewalk line, which sets off row of more important townhouses to the north.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up()Densely Built Up(✓)
Residential()Commercial()
Agricultural()Industrial()
Roadside Strip Development()
Other:

RECORDED BY:


Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



MARYLAND

AVENUE

GEORGE STREET

STREET

RCLE

FRANCIS ST

CORN HILL STREET

FLEET STREET

EAST STREET

PINKNEY STREET

GEORGE STREET


MARTIN

MARKET SP.

RANDALL STREET

COMPTON ST

AA 1161
ANNAPOLIS HIST. DIST.





147 Prince George AA1161
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
NW Elevation/camera facing SE