

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <i>AA 1234</i>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <i>Apartments</i>
ORIGINAL USE: <i>SF Res</i>
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()
THEME:
STYLE: <i>Second Empire</i>
DATE BUILT: <i>c.1870s</i>

COUNTY: <i>Anne Arundel</i>
TOWN: <i>Annapolis</i>
LOCATION: <i>238 Prince George</i>
COMMON NAME:
FUNCTIONAL TYPE: <i>Res Map31 Par48</i>
OWNER: <i>Constance W. Stringer</i>
ADDRESS: <i>238 Prince George Annapolis, MD 21401</i>
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (X) State () National () <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (X) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon (X)
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle (X) Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer () Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: _____ Other: _____
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle (X) Asphalt Shingle () Sheet Metal ()
 Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers (X) Chimneys (X) Sheds () Ells (X)
 Wings () Other:

Roof Style: Gable () Hip () Shed () Flat () Mansard (X) Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 3

Number of Bays: 3 Entrance Location: Right

Approximate Dimensions: 24x60

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Mansard roof with fishscale shingles, pedimented dormers with eared architraves, molded curb, bracketed cornice; triangular window caps, transom lit door with classic revival porch at entrance, which has sidelights.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Part of a pair of good Victorian Mansard residences, important as a type and important to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up()Densely-Built Up()
Residential()Commercial()
Agricultural()Industrial()
Roadside Strip Development()
Other:

RECORDED BY:

Russell Wright

ORGANIZATION:


Historic Annapolis, Inc

DATE RECORDED:

Aug 1983



AA 1234
ANNAPOLIS HIST. DIST.





238 Prince George

AA 1234

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

sw Elevation/camera facing NE