

AA-1322

MARYLAND HISTORICAL TRUST
21 STATE CIRCLE
SHAW HOUSE
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
Individual Structure Survey Form

SURVEY NUMBER: <u>AA 647, 1322</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: Office
ORIGINAL USE: Office
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (<input checked="" type="checkbox"/>) Fair () Poor: ()
THEME:
STYLE: Vernacular
DATE BUILT: 1868

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 3 School Street
COMMON NAME:
FUNCTIONAL TYPE: Comm Map 32 Par 615
OWNER: E. Jefferson Crum & K. Aarsand ADDRESS: 280 Rugby Court Arnold, MD 21012
ACCESSIBILITY TO PUBLIC: Yes (<input checked="" type="checkbox"/>) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (<input checked="" type="checkbox"/>) State () National (<input type="checkbox"/>)

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone () Brick () Concrete () Concrete Block ()
2. Wall Structure
 - A. Wood Frame: Post and Beam () Balloon ()
 - B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other:
3. Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
Brick Veneer () Stone Veneer () Asbestos Shingle ()
Bonding Pattern: _____ Other: _____
4. Roof Structure
 - A. Truss: Wood () Iron () Steel () Concrete ()
 - B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal ()
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds () Ells ()
Wings () Other:

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
Other:

Number of Stories: 1
Number of Bays: 2 Entrance Location: Right
Approximate Dimensions: 10 x 15

THREAT TO STRUCTURE: No Threat (<input checked="" type="checkbox"/>) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

No architectural significance.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane()Woodland()Scattered Buildings()
- Moderately Built Up()Densely-Built Up(✓)
- Residential()Commercial()
- Agricultural()Industrial()
- Roadside Strip Development()
- Other:

RECORDED BY:

Russell Wright


ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983

Form 10-445
(5/62)

<p>1. STATE Annapolis, Maryland COUNTY TOWN VICINITY STREET NO. 1, 3 School Street</p> <p>ORIGINAL OWNER ORIGINAL USE residential, 3 - office PRESENT OWNER PRESENT USE residential, 3 - office WALL CONSTRUCTION asphalt siding NO. OF STORIES 2, 3 - one storey</p>	<p>HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY</p> <p>2. NAME</p> <p>DATE OR PERIOD c. 1860s - 70s STYLE Victorian ARCHITECT BUILDER</p> <p>3. FOR LIBRARY OF CONGRESS USE</p>
<p>4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no</p> <p>1 - a residential two storey 19th C. house with very fine Victorian detail - bracketed cornice with modillions, marvelous window sash (windows 2/2) and a rather special door - see photos. A good example of its type, this house is even more special being located where street and circle meet, thus side isn't perpendicular to street, forming an interesting visual arrangement - the stuff that makes Annapolis visually exciting and non-boring. No. 3, a stock brokers office is good example of period office attached to residence and still used.</p>	
<p>5. PHYSICAL CONDITION OF STRUCTURE</p>	 <p style="text-align: right;">good</p>
<p>6. LOCATION MAP (Plan Optional)</p> <p>8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.</p>	<p>7. PHOTOGRAPH</p> <p>9. NAME, ADDRESS AND TITLE OF RECORDER</p> <p>William D. Morgan Columbia University New York City</p> <p>DATE OF RECORD June 29, 1967</p>

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



3 School St.

AA 1322

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

NW Elevation/camera facing SE