

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: AA 1381
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>Single Family Residence</u>
ORIGINAL USE: <u>Kitchen or Servants' quarters</u>
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (<input checked="" type="checkbox"/>) Fair () Poor: ()
THEME:
STYLE: <u>Georgian - now Victorian</u>
DATE BUILT: <u>c.1765 altered c.1870</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>76 Shipwright</u>
COMMON NAME: <u>Scott Cottage</u>
FUNCTIONAL TYPE: <u>Map 33Par 34</u>
OWNER: <u>Norman & Marianna Heaney</u>
ADDRESS: <u>76 Shipwright</u> <u>21401</u>
ACCESSIBILITY TO PUBLIC: Yes (<input checked="" type="checkbox"/>) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (<input checked="" type="checkbox"/>) State () National (<input type="checkbox"/>)

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick () Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer () Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Flemish Other:
- Roof Structure
 - Truss: Wood () Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal ()
 Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds () Ells ()
Wings () Other: Bay Unit @ rear or north wall, Bay @ front wall

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 1½
 Number of Bays: 1x3
 Approximate Dimensions: 15x40
 Entrance Location: @ north elevation

THREAT TO STRUCTURE: No Threat (<input checked="" type="checkbox"/>) Zoning () Roads () Development () Deterioration () Alteration () Other:
--

LOCAL ATTITUDES: Positive () Negative () Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Pedimented wall dormers, heavy molded cornice with returns, timber lintels at side elevations, round headed window at end wall to street, above a three part bay window with paneled aprons. Entrance porch at right bay of left elevation on square pilasters probably later.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Either kitchen of servants quarters for the Upton Scott House, interesting for the c.1880's alterations to what was a simple vernacular structure. Important to the history of the Scott House and contributes to the streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up(✓)Densely-Built Up()
Residential()Commercial()
Agricultural()Industrial()
Roadside Strip Development()
Other:

RECORDED BY:



Russell Wright

ORGANIZATION:


Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



AA 1381
ANNAPOLIS HIST. DIST.





76 Shipwright

AA 1381

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

SW Elevation/camera facing NE



76 Shipwright

AA 1381

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

SW Elevation/camera facing NE