

AA-1400

MARYLAND HISTORICAL TRUST
21 STATE CIRCLE
SHAW HOUSE
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
Individual Structure Survey Form

SURVEY NUMBER: AA 373, 1400
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: Office
ORIGINAL USE: SF Res
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()
THEME:
STYLE: Victorian Mansard, Altered
DATE BUILT: 1908-1913

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 99 Cathedral Street
COMMON NAME:
FUNCTIONAL TYPE: Res Map 30 Par 564
OWNER: Ben D. & Virginia M. Conley ADDRESS: 1919 West Street Annapolis, MD 21401
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (✓) State () National ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (X) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon (X)
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
Novelty () Stucco () Sheet Metal () Aluminum (X) Asphalt Shingle ()
Brick Veneer () Stone Veneer () Asbestos Shingle ()
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate (X) Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers (X) Chimneys (X) Sheds () Ells ()
Wings () Other: Porch infilled

Roof Style: Gable () Hip () Shed () Flat () Mansard (X) Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
Other:

Number of Stories: 3
Number of Bays: 3 x 2
Approximate Dimensions: 20 x 55

Entrance Location: Right

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-1400

Excellent pedimented dormers with applied sunbursts in gables, on patterned shingle false Mansard roof; good bracketed cornice with end consoles; transom lit door; Porch has been infilled and entire structure covered with aluminum siding.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of false Mansard Second Empire marred by siding and infilled porch. One of a pair with 97 Cathedral.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
 Moderately Built Up()Densely-Built Up(✓)
 Residential()Commercial()
 Agricultural()Industrial()
 Roadside Strip Development()
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983

Form 10-445 (5/62)

<p>1. STATE Annapolis, Maryland COUNTY TOWN VICINITY STREET NO. 99, 97 Cathedral St. (2bld)</p> <p>ORIGINAL OWNER ORIGINAL USE residences PRESENT OWNER PRESENT USE residences WALL CONSTRUCTION shingle (97 moderns) NO. OF STORIES two plus mansard attic</p>	<p>HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY</p> <p>2. NAME</p> <p>DATE OR PERIOD 1880, - 90s STYLE Victorian ARCHITECT BUILDER</p> <p>3. FOR LIBRARY OF CONGRESS USE</p>
---	---

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no

This pair are a fine Victorian couple. Though identical both add to the street and are worth preserving as a unit. Good examples of Victorian residences which are large and usable while presenting imposing street facades. They sit up on c3' basements, have front porches held up by 4 slim pillars and decorated with scalloping, 3 second storey windows (2/2), with modillioned, bracketed, and scalloped cornices. The outstanding feature of these houses is their "applied" mansard roof making up the 3rd storey. The mansard is of slate with a decorative diamond pattern running through the middle. There are two slightly projecting dormers on both with abstracted sun bursts on the pediment. Topped by small plain cornice - flat roof. Both basically unaltered except for 97's new siding, 99's brown shingling is original and is superb. Very handsome.



*Ca. 1910
 Naval Academy
 Beauty Arts*

good


7. PHOTOGRAPH

<p>8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.</p>	<p>9. NAME, ADDRESS AND TITLE OF RECORDER</p> <p>William D. Morgan Columbia University New York City</p> <p>DATE OF RECORD June 22, 1967</p>
---	--

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



AA 1460
ANNAPOLIS HIST. DIST.



ST. JOHN'S STREET

BLADEN STREET

CARROLL STREET

NORTHWEST STREET

CALVERT STREET

CATHEDRAL STREET

WASHINGTON STREET

WESLEY STREET

WATER STREET

CITY GATE LANE

SHAW STREET

COLLEGE

SCHOOL ST.

STATE CIRCLE

CHURCH CIRCLE

DUKE STREET

SHAW STREET

ACTON STREET

SOUTH STREET

CHARLES STREET



99 Cathedral

AA 1400

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

MWElevation/camera facing SE

J2 28