

AA-1444

38 Murray Avenue
Annapolis
Private

1913-1921

A rare example of the Bungalow style, 38 Murray Avenue is one and one-half stories with a steep gable roof parallel to the street that has a three bay shed dormer with 6/6 sash. The lower plane of the roof projects to enclose a full width front porch area, with square posts and infilled wall below rail height, all of which is clapboard as is the rest of the residence. Windows in the first floor front are 6/6, arranged in a row of three and cased with molded lintel caps, repeated at the right bay entrance. Windows in the side elevations are 6/6 but single. Rectangular in plan, 25' x 32', 2 x 2 bays, the frame structure has a one bay wide, one story rear porch. The overhanging roof of the house and the dormer is supported with sawn open braces at the purlin lines.

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. AA 1444
Magi No.
DOE yes no

1. Name (indicate preferred name)

historic

and/or common

2. Location

street & number 38 Murray Avenue not for publication

city, town Annapolis vicinity of congressional district 30th

state Maryland county Anne Arundel

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input checked="" type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Caldwell Dorothy V

street & number 38 Murray Avenue telephone no.:

city, town Annapolis state and zip code MD 21401

5. Location of Legal Description

courthouse, registry of deeds, etc. Anne Arundel Cty Courthouse liber

street & number Church Circle folio

city, town Annapolis state Maryland

6. Representation in Existing Historical Surveys

title Historic Annapolis, Inc.

date Sept. 1983 federal state county local

pository for survey records 194 Prince George St.

city, town Annapolis state Maryland

7. Description

Survey No. AA-1444

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

A rare example of the Bungalow style, 38 Murray Avenue is one and one-half stories with a steep gable roof parallel to the street that has a three bay shed dormer with 6/6 sash. The lower plane of the roof projects to enclose a full width front porch area, with square posts and infilled wall below rail height, all of which is clapboard as is the rest of the residence. Windows in the first floor front are 6/6, arranged in a row of three and cased with molded lintel caps, repeated at the right bay entrance. Windows in the side elevations are 6/6 but single. Rectangular in plan, 25' x 32', 2 x 2 bays, the frame structure has a one bay wide, one story rear porch. The overhanging roof of the house and the dormer is supported with sawn open braces at the purlin lines.

8. Significance

Survey No. AA 1444

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates 1913 - 1921

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

Fair example of a Bungalow style, contributing to variety of street-sc ape through scale and setback.

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 1444</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>Single Family Residence</u>
ORIGINAL USE: " " "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good () Fair () Poor: ()
THEME:
STYLE: <u>Bungalow</u>
DATE BUILT: <u>1913-1921</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>38 Murray Avenue</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map 30 Par 467</u>
OWNER: <u>Caldwell Dorothy V</u> ADDRESS: <u>38 Murray Ave</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (✓) State () National () <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick () Concrete () Concrete Block (X)
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard (X) Board and Batten () Wood Shingle () Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer () Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: _____ Other: _____
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal ()
 Built Up () Rolled () Tile () Other: Asbestos
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers (X) Chimneys (X) Sheds () Ells (X)
 Wings () Other:

Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 2
 Number of Bays: 3 Entrance Location: Right
 Approximate Dimensions: 25x32

THREAT TO STRUCTURE: No Threat () Zoning () Roads () Development () Deterioration () Alteration () Other:
--

LOCAL ATTITUDES: Positive () Negative () Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Large shed roof dormer with three 6/1 sash; triple window to left of entrance; roof extends to protect full width porch.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Fair example of Bungalow style, contributing to variety of streetscape through scale and setback.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane() Woodland() Scattered Buildings()
Moderately Built Up(/) Densely-Built Up()
Residential() Commercial()
Agricultural() Industrial()
Roadside Strip Development()
Other:

RECORDED BY:


Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:


AUG. 1983



AA 1444
ANNAPOLIS HIST. DIST.

NORTHWEST

STR





38 Murray

AA 1444

Annapolis, Anne Arundel County

Russell Wright

July, 1982

Maryland Historical Trust,

Annapolis, Maryland

SW Elevation/camera facing ne

M34