

47 Southgate Avenue  
Annapolis  
Private

1908-1913

This hipped roof two and one-half story Flemish bond brick structure has a Palladian window central dormer, with flanking dormers of traditional size and fenestration. The first floor of the front facade has an excellent segmental fan and sidelit entrance in the central bay, with leaded tracery, protected by a full width one story porch supported on Tuscan columns, with a molded hand rail and square balusters. The central part of the porch breaks and extends over the brick stair, with duplicate Tuscan columns resting on the brick cheek walls. The porch extends along the left side elevation, terminating at an octagonal bay unit, with four 6/1 sash. The second floor of the front elevation has a single 6/1 central window flanked by a tripartite 4/1-6/1-4/1 unit. A two bay ell at the right elevation, rear, has two 6/1 windows in the second level and a pedimented entrance. The hipped roof has a molded cornice without frieze and is sheathed with slate. The rear section has a separate hipped roof. The Georgian Revival residence is rectangular in plan, 45' x 50', and is 3 by 3 bays.

# Maryland Historical Trust State Historic Sites Inventory Form

Survey No.

AA 1469

Magi No.

DOE  yes  no

## 1. Name (indicate preferred name)

historic

and/or common

## 2. Location

street & number 47 Southgate Ave.  not for publicationcity, town Annapolis  vicinity of congressional district 30thstate Maryland  county Anne Arundel

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name Cecil &amp; Martha Knighton

street &amp; number 47 Southgate Ave. telephone no.:

city, town Annapolis state and zip code MD 21401

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Anne Arundel Cty Courthouse liber

street &amp; number Church Circle folio

city, town Annapolis state Maryland

## 6. Representation in Existing Historical Surveys

title Historic Annapolis, Inc.

date Sept. 1983  federal  state  county  local

pository for survey records 194 Prince George St.

city, town Annapolis state Maryland

# 7. Description

Survey No. AA-1469

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved    date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This hipped roof two and one-half story Flemish bond brick structure has a Palladian window central dormer, with flanking dormers of traditional size and fenestration. The first floor of the front facade has an excellent segmental fan and sidelit entrance in the central bay, with leaded tracery, protected by a full width one story porch supported on Tuscan columns, with a molded hand rail and square balusters. The central part of the porch breaks and extends over the brick stair, with duplicate Tuscan columns resting on the brick cheek walls. The porch extends along the left side elevation, terminating at an octagonal bay unit, with four 6/1 sash. The second floor of the front elevation has a single 6/1 central window flanked by a tripartite 4/1-6/1-4/1 unit. A two bay ell at the right elevation, rear, has two 6/1 windows in the second level and a pedimented entrance. The hipped roof has a molded cornice without frieze and is sheathed with slate. The rear section has a separate hipped roof. The Georgian Revival residence is rectangular in plan, 45' x 50', and is 3 by 3 bays.

# 8. Significance

Survey No. AA 1469

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

**Specific dates** 1908 - 1913 **Builder/Architect**

check: Applicable Criteria:  A  B  C  D  
and/or  
Applicable Exception:  A  B  C  D  E  F  G

Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

Good example of Neo-Georgian style, contributes to streetscape.



MARYLAND HISTORICAL TRUST  
 21 STATE CIRCLE  
 SHAW HOUSE  
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 1469</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>SF Res</u>
ORIGINAL USE: <u>SF Res</u>
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent (X) Good ( ) Fair ( ) Poor: ( )
THEME:
STYLE: <u>Georgian Revival</u>
DATE BUILT: <u>1908-1913</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>47 Southgate Avenue</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map 29 Par 127</u>
OWNER: <u>Cecil &amp; Martha Knighton</u>
ADDRESS: <u>47 Southgate Avenue</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (X) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local (✓) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone ( ) Brick (X) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood Frame: Post and Beam ( ) Balloon ( )
  - Wood Bearing Masonry: Brick (X) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other:
- Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
Novelty ( ) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
Brick Veneer (X) Stone Veneer ( ) Asbestos Shingle ( )  
Bonding Pattern: Common Other:
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate (X) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers (X) Chimneys (X) Sheds ( ) Ells (X)  
Wings (X) Other:

Roof Style: Gable ( ) Hip (X) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
Other:

Number of Stories: 2 1/2

Number of Bays: 3 x 3 Entrance Location: Centered

Approximate Dimensions: 45 x 50

THREAT TO STRUCTURE: No Threat (X) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:	LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-1469

Hipped dormer at front with triple window, full width porch with turned columns; sidelit entrance.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of Neo-Georgian style, contributes to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane( ) Woodland( ) Scattered Buildings( )  
Moderately Built Up(✓) Densely Built Up( )  
Residential( ) Commercial( )  
Agricultural( ) Industrial( )  
Roadside Strip Development( )  
Other:

RECORDED BY:


Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



AA 1469  
ANNAPOLIS HIST. DIST.

NORTHWEST

STR





AA 28

47 Southgate                      AA 1469  
Annapolis, Anne Arundel County  
Russell Wright                      July, 1982  
Maryland Historical Trust,  
Annapolis, Maryland  
nw Elevation/camera facing se



47 Southgate

AA 1469

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

nw Elevation/camera facing se

K 2 29