

AA-1501

74 Southgate Avenue  
Annapolis  
Private

Post 1930

A gable roof with hipped two bay front dormer, two and one-half stories vernacular residence, 74 Southgate is a stucco on frame structure with a full width front porch, one story with a hipped roof and square corner posts. Windows in the second floor front are paired, triple at the first to the right of the entrance. All other windows are set singly, and are 6/1. A one story rectangular bay unit is located at the rear of the right elevation and there is a one bay, one story porch at the right half of the rear facade. Rectangular in plan, 25' x 35', two by two bays, the residence has a garage in the rear of no significance.

Survey No. AA 1501

Magi No.

DOE \_\_\_yes \_\_\_no

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic

and/or common

## 2. Location

street & number 74 Southgate Ave. \_\_\_ not for publication

city, town Annapolis \_\_\_ vicinity of congressional district 30th

state Maryland county Anne Arundel

## 3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input checked="" type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military
			<input type="checkbox"/> museum
			<input type="checkbox"/> park
			<input type="checkbox"/> private residence
			<input type="checkbox"/> religious
			<input type="checkbox"/> scientific
			<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name Ray Williamson

street & number 74 Southgate Ave. telephone no.:

city, town Annapolis state and zip code MD 21401

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Anne Arundel Cty Courthouse liber

street & number Church Circle folio

city, town Annapolis state Maryland

## 6. Representation in Existing Historical Surveys

title Historic Annapolis, Inc.

date Sept. 1983 \_\_\_ federal \_\_\_ state \_\_\_ county  local

pository for survey records 194 Prince George St.

city, town Annapolis state Maryland

# 7. Description

Survey No. AA-1501

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

A gable roof with hipped two bay front dormer, two and one-half stories vernacular residence, 74 Southgate is a stucco on frame structure with a full width front porch, one story with a hipped roof and square corner posts. Windows in the second floor front are paired, triple at the first to the right of the entrance. All other windows are set singly, and are 6/1. A one story rectangular bay unit is located at the rear of the right elevation and there is a one bay, one story porch at the right half of the rear facade. Rectangular in plan, 25' x 35', two by two bays, the residence has a garage in the rear of no significance.





MARYLAND HISTORICAL TRUST  
 21 STATE CIRCLE  
 SHAW HOUSE  
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 1501</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: SF Res
ORIGINAL USE: SF Res
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (X) Fair ( ) Poor: ( )
THEME:
STYLE: <u>Homestead</u>
DATE BUILT: <u>post 1930</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>74 Southgate Avenue</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map 30Par 408</u>
OWNER: <u>Ray Williamson</u>
ADDRESS: <u>74 Southgate Avenue</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (X) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local ( ) State ( ) National ( ) <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone ( ) Brick ( ) Concrete ( ) Concrete Block (X)
- Wall Structure
  - Wood Frame: Post and Beam ( ) Balloon (X)
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other:
- Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
 Novelty ( ) Stucco (X) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
 Brick Veneer ( ) Stone Veneer ( ) Asbestos Shingle ( )  
 Bonding Pattern: \_\_\_\_\_ Other: \_\_\_\_\_
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate (X) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal ( )  
 Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers (X) Chimneys (X) Sheds ( ) Ells (X)  
 Wings (X) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
 Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
 Other:

Number of Stories: 2 1/2  
 Number of Bays: 2 x 2  
 Approximate Dimensions: 22 x 30

Entrance Location: Left

THREAT TO STRUCTURE: No Threat (X) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:	LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Hipped dormer with paired windows, paired windows at second floor, full width porch with square pilasters.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Contributes to streetscape, minor variant of Homestead style.

REFERENCES:

MAP: (Indicate North In Circle)




SURROUNDING ENVIRONMENT:

- Open Lane( ) Woodland( ) Scattered Buildings( )
- Moderately Built Up(✓) Densely-Built Up( )
- Residential( ) Commercial( )
- Agricultural( ) Industrial( )
- Roadside Strip Development( )
- Other:

RECORDED BY: Russell Wright


ORGANIZATION: Historic Annapolis, Inc

DATE RECORDED: Aug. 1983



AA 1501  
ANNAPOLIS HIST. DIST.

NORTHWEST STR





74 Southgate AA1501  
Annapolis, Anne Arundel County  
Russell Wright July, 1982  
Maryland Historical Trust,  
Annapolis, Maryland  
sw Elevation/camera facing ne

P7