

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA1590</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>Offices</u>
ORIGINAL USE: <u>Offices/Apartments</u>
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good () Fair (X) Poor ()
THEME:
STYLE: <u>Victorian Italianate</u>
DATE BUILT: <u>c.1880</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>5 State Circle</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Comm Map 32 Par 322</u>
OWNER: <u>Pannoni Fausto & Rose G/% John Patten</u>
ADDRESS: <u>500 Dogwood Rd. Linthicum, MD 21090</u>
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (X) State () National ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick (X) Concrete () Concrete Block ()
- Wall Structure
 - Wood Frame: Post and Beam () Balloon ()
 - Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle () Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer (X) Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Common Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal ()
 Built Up () Rolled (X) Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds () Ells ()
 Wings () Other:

Roof Style: Gable () Hip () Shed (X) Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 2 on tall cellar

Number of Bays: 3

Approximate Dimensions: 25 x 65

Entrance Location: Left

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:
--	---

9A-1590

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Bracketed cornice with paired end consoles, jig sawn panels in frieze, elliptical windows at first and second floor, first floor reached by later stair.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Minor example of Italianate Commercial but important to the streetscape as it starts the circle arrangement of buildings.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane() Woodland() Scattered Buildings()
- Moderately Built Up() Densely-Built Up(✓)
- Residential() Commercial()
- Agricultural() Industrial()
- Roadside Strip Development()
- Other:

RECORDED BY:



Russell Wright

ORGANIZATION:



Historic Annapolis, Inc

DATE RECORDED:

Aug 1983



AA 1590
ANNAPOLIS HIST. DIST.





5 State Circle

AA 1590

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

NW Elevation/camera facing SE