

MARYLAND HISTORICAL TRUST  
 21 STATE CIRCLE  
 SHAW HOUSE  
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
 Individual Structure Survey Form

SURVEY NUMBER: <b>AA <del>1623</del> 1623</b>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: SF Res
ORIGINAL USE: SF Res
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (X) Fair ( ) Poor: ( )
THEME:
STYLE: Second Empire
DATE BUILT: c.1870s

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 26 Randall Street
COMMON NAME:
FUNCTIONAL TYPE: Res Map34 Par 42
OWNER: Helen C. Stinchcomb
ADDRESS: 26 Randall Street Annapolis, MD 21401
ACCESSIBILITY TO PUBLIC: Yes (X) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local (✓) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ( ) Brick (X) Concrete ( ) Concrete Block ( )
2. Wall Structure
  - A. Wood Frame: Post and Beam ( ) Balloon (X)
  - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - C. Iron ( ) D. Steel ( ) E. Other:
3. Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
 Novelty ( ) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
 Brick Veneer ( ) Stone Veneer ( ) Asbestos Shingle (X)  
 Bonding Pattern: Other:
4. Roof Structure
  - A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - B. Other:
5. Roof Covering: Slate (X) Wood Shingle ( ) Asphalt Shingle (X) Sheet Metal ( )  
 Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers (X) Chimneys (X) Sheds ( ) Ells (X)  
 Wings ( ) Other: Side bay unit

Roof Style: Gable ( ) Hip ( ) Shed ( ) Flat ( ) Mansard (X) Gambrel ( ) Jerkinhead ( )  
 Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
 Other:

Number of Stories: 3  
 Number of Bays: 3  
 Approximate Dimensions: 20 x 50

Entrance Location: Right

THREAT TO STRUCTURE: No Threat (X) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:
--

LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:
---

AA-1623

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Full Mansard roof with gabled dormers at side and outside bay, paired and split at the center of double house; wood curb and bracketed cornice, molded caps at windows and door, which is transom and side lighted; full width porch on turned columns with jig sawn braces.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

One half of a good Second Empire pair, important as a type and important to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane( )Woodland( )Scattered Buildings( )
- Moderately Built Up( )Densely-Built Up(✓)
- Residential( )Commercial( )
- Agricultural( )Industrial( )
- Roadside Strip Development( )
- Other:

RECORDED BY:


Russell Wright

ORGANIZATION:



Historic Annapolis, Inc

DATE RECORDED:

Aug 1983



AA 1623  
ANNAPOLIS HIST. DIST.





26 Randall AA 1623  
Annapolis, Anne Arundel County  
Russell Wright July, 1982  
Maryland Historical Trust,  
Annapolis, Maryland  
NE Elevation/camera facing SW