

MARYLAND HISTORICAL TRUST  
21 STATE CIRCLE  
SHAW HOUSE  
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
Individual Structure Survey Form

SURVEY NUMBER: <u>AA 1651</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>single Family Residence</u>
ORIGINAL USE: " " "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (x) Fair ( ) Poor: ( )
THEME:
STYLE: <u>Vernacular-Annapolis Federal</u>
DATE BUILT: <u>1891-1897</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>84 Market</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map 33 Par 1</u>
OWNER: <u>Seamon Richard M &amp; Nancy</u>
ADDRESS: <u>84 Market St.</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (x) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local (x) State ( ) National ( ) <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ( ) Brick (x) Concrete ( ) Concrete Block ( )
2. Wall Structure
  - A. Wood Frame: Post and Beam ( ) Balloon (xx)
  - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - C. Iron ( ) D. Steel ( ) E. Other:
3. Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
Novelty (x) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
Brick Veneer ( ) Stone Veneer ( ) Asbestos Shingle ( )  
Bonding Pattern: \_\_\_\_\_ Other: \_\_\_\_\_
4. Roof Structure
  - A. Truss: Wood (x) Iron ( ) Steel ( ) Concrete ( )
  - B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (x)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ( ) Towers ( ) Cupolas ( ) Dormers (x) Chimneys (x) Sheds ( ) Ells ( )  
Wings ( ) Other: Later Bay Wundiw @ left, first elevation; later dormer.

Roof Style: Gable (x) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
Other:

Number of Stories: 2 1/2  
Number of Bays: 3x2  
Approximate Dimensions: 18x50

Entrance Location: Right

THREAT TO STRUCTURE:  
No Threat (x) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Large double dormer with hipped roof at standing seam roof; bracketed cornice with deep frieze panel, molded caps at all windows, including those in three-part projecting bay at first floor and at transom lit entrance; door good Italianate round headed panel.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Altered but good example of late 19thC Italianate Vernacular construction, important to streetscape.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane( ) Woodland( ) Scattered Buildings( )
- Moderately Built Up(✓) Densely Built Up( )
- Residential( ) Commercial( )
- Agricultural( ) Industrial( )
- Roadside Strip Development( )
- Other:

RECORDED BY:


Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



AA 1651  
ANNAPOLIS HIST. DIST.

0 50 100 200 300 400 500 SCALE IN FEET



84 Mkt

AA 1651

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

NE Elevation/camera facing sw

84 MKT