

AA-1888

23 Thompson Street
Annapolis
Private

1913-21

An excellent Homestead style residence, this two and one-half story frame structure has a gable roof perpendicular to the street, with molded rakes that return. The gabled section of the front wall is raised slightly from the main body, creating a pedimented visual effect. There is a paired 6/1 window arrangement in the gable end, and paired windows in the right and left bays of the second floor front. Windows at the first floor are triple 6/1, to the left of the entrance, and a smaller casement lighting the stair to the right of the entrance and hall. A full width front porch, one story with a standing seam low hipped roof, has Tuscan columns, molded handrails and square balusters, and rests on an infilled (concrete block) base. The entire frame structure is shingled, and is rectangular in plan, 30' x 35', with a one story, one bay wide rear porch. There is a one story garage at the rear of no importance.

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. AA 1888

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic

and/or common

2. Location

street & number 23 Thompson St. not for publication

city, town Annapolis vicinity of congressional district 30th

state Maryland county Anne Arundel

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input checked="" type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Robert & Judith Moore

street & number 23 Thompson St. telephone no.:

city, town Annapolis state and zip code MD 21401

5. Location of Legal Description

courthouse, registry of deeds, etc. Anne Arundel Cty Courthouse liber

street & number Church Circle folio

city, town Annapolis state Maryland

6. Representation in Existing Historical Surveys

title Historic Annapolis, Inc.

date Sept. 1983 federal state county local

pository for survey records 194 Prince George St.

city, town Annapolis state Maryland

7. Description

Survey No. AA-1888

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

An excellent Homestead style residence, this two and one-half story frame structure has a gable roof perpendicular to the street, with molded rakes that return. The gabled section of the front wall is raised slightly from the main body, creating a pedimented visual effect. There is a paired 6/1 window arrangement in the gable end, and paired windows in the right and left bays of the second floor front. Windows at the first floor are triple 6/1, to the left of the entrance, and a smaller casement lighting the stair to the right of the entrance and hall. A full width front porch, one story with a standing seam low hipped roof, has Tuscan columns, molded handrails and square balusters, and rests on an infilled (concrete block) base. The entire frame structure is shingled, and is rectangular in plan, 30' x 35', with a one story, one bay wide rear porch. There is a one story garage at the rear of no importance.

8. Significance

Survey No. AA 1888

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates 1913 - 1921 **Builder/Architect**

check: Applicable Criteria: A B C D
and/or
Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

Good example of 20thC vernacular of a somewhat larger scale, yet complimenting streetscape because of setback, form, and use of materials.

9. Major Bibliographical References

Survey No. AA-1888

10. Geographical Data

Acreage of nominated property _____

Quadrangle name _____

Quadrangle scale _____

UTM References do NOT complete UTM references

A
 Zone Easting Northing

B
 Zone Easting Northing

C

D

E

F

G

H

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
N/A			

state	code	county	code

11. Form Prepared By

name/title Russell Wright, Consultant

organization Historic Annapolis, Inc. date Sept. 1983

street & number 194 Prince George St. telephone (301) 267-7619

city or town Annapolis state Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: AA 1888
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: SF Res
ORIGINAL USE: SF Res
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()
THEME:
STYLE: Vernacular
DATE BUILT: 1913-1921

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 23 Thompson Street
COMMON NAME:
FUNCTIONAL TYPE: Res Map 29 Par 228
OWNER: Robert & Judith Moore
ADDRESS: 23 Thompson Street Annapolis, MD 21401
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (✓) State () National ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone () Brick () Concrete () Concrete Block (X)
- Wall Structure
 - Wood Frame: Post and Beam () Balloon (X)
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other:
- Wall Covering: Clapboard () Board and Batten () Wood Shingle (X) Shiplap ()
 Novelty () Stucco () Sheet Metal () Aluminum () Asphalt Shingle ()
 Brick Veneer () Stone Veneer () Asbestos Shingle ()
 Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
 Built Up () Rolled () Tile () Other: Porch has standing seam S.M. roof.
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys (X) Sheds () Ells (X)
 Wings () Other:

Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet () With False Front ()
 Other:

Number of Stories: 2 1/2
 Number of Bays: 2
 Approximate Dimensions: 30 x 35
 Entrance Location: Right

THREAT TO STRUCTURE: No Threat (X) Zoning () Roads () Development () Deterioration () Alteration () Other:
--

LOCAL ATTITUDES: Positive () Negative () Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-1888

Projecting street end gable with molded wood rake boards and returns; paired 6/1 sash at upper levels; good 1 x 3 bay low hipped one-story porch with turned Tuscan columns; triple 6/1 sash to left of transom lit entrance.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of 20thC vernacular of a somewhat larger scale, yet complimenting streetscape because of setback, form and use of materials.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane() Woodland() Scattered Buildings()
- Moderately Built Up(✓) Densely-Built Up()
- Residential() Commercial()
- Agricultural() Industrial()
- Roadside Strip Development()
- Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



COLONIAL STREET

STEELE AVENUE

SOUTHGATE AVENUE

THOMPSON STREET

LAFAYETTE AVENUE

MURRAY AVENUE

FRANKLIN STREET

FRANKLIN STREET

FRANKLIN STREET

FRANKLIN STREET

CHESTON AVENUE

TANEY AVENUE

ACTON PLACE



ACTON PLACE

SHAW STREET

SHAW STREET

AA 1888
ANNAPOLIS HIST. DIST.

SCALE IN FEET





23 Thompson AA 1888
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
sc Elevation/camera facing nw

H1 17