

AA-1945

119 Clay Street  
Annapolis  
Private

c.1921-30

119 Clay Street is a two and one-half story hipped roof with small casement lit dormer Four Square style residence. The front elevation (north) has paired 6/1 sash in each of two bays, the first floor a glass paneled entrance door flanked by a narrow window to light the stair at the right and a triple 6/1 window at the left. The first floor is protected by a full width porch with hipped roof supported on turned Tuscan columns with a molded handrail and square balusters. The deeply overhanging eaves had a frieze, now hidden by the later asbestos shingles. A one bay wide one story rear entrance porch is appended to the southwest corner of the rear facade.

# Maryland Historical Trust State Historic Sites Inventory Form

Survey No. AA 1945

Magi No.

DOE  yes  no

## 1. Name (indicate preferred name)

historic

and/or common

## 2. Location

street & number 119 Clay Street

not for publication

city, town Annapolis

vicinity of

congressional district

30th

state Maryland

county

Anne Arundel

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name Hill Burma L.

street & number 9201 Gary Lane

telephone no.:

city, town Landover

state and zip code Maryland 20785

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Anne Arundel Cty Courthouse

liber

street & number

Church Circle

folio

city, town

Annapolis

state

Maryland

## 6. Representation in Existing Historical Surveys

title Historic Annapolis, Inc.

date Sept. 1983

federal  state  county  local

pository for survey records 194 Prince George St.

city, town Annapolis

state Maryland

# 7. Description

Survey No. AA-1945

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

119 Clay Street is a two and one-half story hipped roof with small casement lit dormer Four Square style residence. The front elevation (north) has paired 6/1 sash in each of two bays, the first floor a glass paneled entrance door flanked by a narrow window to light the stair at the right and a triple 6/1 window at the left. The first floor is protected by a full width porch with hipped roof supported on turned Tuscan columns with a molded handrail and square balusters. The deeply overhanging eaves had a frieze, now hidden by the later asbestos shingles. A one bay wide one story rear entrance porch is appended to the southwest corner of the rear facade.

# 8. Significance

Survey No. AA 1945

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

**Specific dates** 1921 - 1930 **Builder/Architect**

check: Applicable Criteria:  A  B  C  D  
and/or

Applicable Exception:  A  B  C  D  E  F  G

Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

Good example of Four-Square residence with original porch. End structure of a row of four similar buildings that establishes the streetscape and character of this part of Clay Street.



MARYLAND HISTORICAL TRUST  
 21 STATE CIRCLE  
 SHAW HOUSE  
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
 Individual Structure Survey Form

SURVEY NUMBER: AA 1945	
NEGATIVE FILE NUMBER:	
UTM REFERENCES: Zone/Easting/Northing	
U.S.G.S. QUAD. MAP:	
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE: SF Res	
ORIGINAL USE: SF Res	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good ( ) Fair (x) Poor: ( )	
THEME:	
STYLE: Four Square	
DATE BUILT: 1921-1930	

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 119 Clay
COMMON NAME:
FUNCTIONAL TYPE: RES Map 30 Par 310
OWNER: Hill Burma L ADDRESS: 9201 Gary Lane Landover MD 20785
ACCESSIBILITY TO PUBLIC: Yes (x) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local (x) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone ( ) Brick ( ) Concrete ( ) Concrete Block (x)
- Wall Structure
  - Wood Frame: Post and Beam ( ) Balloon (x)
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other:
- Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
 Novelty ( ) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
 Brick Veneer ( ) Stone Veneer ( ) Asbestos Shingle (x)  
 Bonding Pattern: Other:
- Roof Structure
  - Truss: Wood (x) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle (x) Sheet Metal ( )  
 Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (x) Towers ( ) Cupolas ( ) Dormers (x) Chimneys (x) Sheds ( ) Ells (x)  
 Wings ( ) Other:

Roof Style: Gable ( ) Hip (x) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
 Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
 Other:

Number of Stories: 2½  
 Number of Bays: 2 x 2  
 Approximate Dimensions: 20 x 30  
 Entrance Location: Right

THREAT TO STRUCTURE: No Threat (x) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:
--

LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:
---

AA-1945

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Good example of Four-Square style with hipped roof dormer, full width porch, triple window at first floor, paired above. Asbestos siding.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of Four-Square residence with original porch. End structure of a row of four similar buildings that establishes the streetscape and character of this part of Clay Street.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane( ) Woodland( ) Scattered Buildings( )
- Moderately Built Up(✓) Densely-Built Up( )
- Residential( ) Commercial( )
- Agricultural( ) Industrial( )
- Roadside Strip Development( )
- Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



AA 1945  
ANNAPOLIS HIST. DIST.

NORTHWEST STR





119 Clay St.

AA 1945

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

NW Elevation/camera facing SE

F2

34