

**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes ___
no

Property Name: Dove Property Inventory Number: AA-2107
 Address: 1332 Rossback Road City: Davidsonville Zip Code: 21035
 County: Anne Arundel USGS Topographic Map: Davidsonville
 Owner: Mr. Richard E. Dove Jr & Billie L. Dove Is the property being evaluated a district? ___ yes
 Tax Parcel Number: 53 Tax Map Number: 49 Tax Account ID Number: 90001209
 Project: Tarnans Branch Stream Restoration Agency: State Highway Administration
 Site visit by MHT staff: no ___ yes Name: _____ Date: _____
 Is the property is located within a historic district ___ yes no

If the property is within a district District Inventory Number: _____
 NR-listed district ___ yes Eligible district ___ yes Name of District: _____
 Preparer's Recommendation: Contributing resource ___ yes ___ no Non-contributing but eligible in another context ___ yes

If the property is not within a district (or the property is a district) Preparer's Recommendation: Eligible ___ yes no

Criteria: ___ A ___ B ___ C ___ D Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G ___ None

Documentation on the property/district is presented in _____

Description of Property and Eligibility Determination *(Use continuation sheet if necessary and attach map and photo)*

The Dove House does not face Rossback Road, but instead is oriented to Tarnans Branch and the adjacent property. It is approximately 1100 feet from Rossback Road and is not visible from the road. There are several outbuildings associated with the property including a barn, cold or ice storage shed, and smaller utilitarian sheds.

The house is a 2 story, side gable home with several additions and alterations. The roof is clad with a composite shingle, pierced by a ridge line chimney and features large gable returns. The 6/6 double hung sash windows are spaced asymmetrically and the house is clad with asbestos siding. There is a small-hipped roof porch on the front façade with Doric posts. Two shed roof additions are on the eastern side of the house. Entrance to the house is through the shed addition. The rear façade illustrates damage by vines and mold. Also, on the rear façade one can see the stone and brick foundation.

This property is considered not eligible for the National Register due to lack of original building materials and that there are better, extant examples of the Greek Revival style applied to a vernacular house.

The Dove house is not considered eligible under Criterion A as there is no known significant historical event associated with this property.

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended ___	Eligibility not recommended <input checked="" type="checkbox"/>
Criteria: ___ A ___ B ___ C ___ D	Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G ___ None
MHT Comments	
<u>Andrew Lewis</u> Reviewer, Office of Preservation Service	<u>1/14/03</u> Date
<u>[Signature]</u> Reviewer, NR Program	<u>1/17/03</u> Date

200204669

NR-ELIGIBILITY REVIEW FORM

Dove Property

Page 2

AA-2107


The Dove House is not considered eligible under Criterion B as there is no known person of significance associated with this house.

The Dove House is not considered eligible under Criterion C as an outstanding example of an architectural style or the work of a master craftsman.

The Dove House is not considered eligible under Criterion D as it is unlikely to contain information that is currently unknown.

Prepared by: Becky Kermes

Date Prepared: 11/20/2002



↑ North
AA-2107

Davidsonville, Anne Arundel

~~Base~~ USGS

Davidsonville

LIBRARY RESERVATION
RADIO TRANSMITTER STATION



HTS

SANDS



Apr - 2007

Time 10:00

Area 1000

Weather 1000, 1000, 1000, 1000

January 2002

Temperature 1000, 1000

Wind 1000, 1000, 1000

View of the sea east of the island as
seen from the "Pier" (1000) in the
(AA-208).

1 of 11



AA-2001

Dove Proximity

Amble in 1991, MP

My

January 2002

Negatives @ 12-11-02

1991 1992 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002

View of the southeast facade with focus
on brick columns.

2 of 11



JA 2107

Dove Property

Arundel, MD

Boris Kermis, owner

January 2002

1.000000 + 1.000000

NET 1.000000

view of the world as a whole with emphasis
on the 2 sides of the coin in the
100% of the world.

3000



AA 2100
1000 1000 1000

Anne Arundel, 117

Barkley Ker 1103, 1103 - 1103
Nashville, TN 37203

January 2002

1103 1103 1103 1103 1103
1103 1103 1103 1103 1103

1103 1103 1103 1103 1103
1103 1103 1103 1103 1103
1103 1103 1103 1103 1103



AD 2101

Dave Proberly

Anne Arundel Co.

Re: by letter of 10/10/02

10/10/02

MD 2101

MD 2101

View of the north end of the road - This is the
end of the road on the left side of the road
at the end of the road. The road is
about 100 feet wide.

5 of 11



AA-2 81

Dov House

Anne Arundel Co.

1700s - 1800s - 1900s

1700s - 1800s

1700s - 1800s

1700s - 1800s

Another view of the roof and elevation.
Note the heavy cornice on the side wall and
cornice on the side wall of the house

1700s



HA-2107

Doc. Property

1000 ft. - 1000

St. John's Kern Co. - 1000 ft. - 1000

2000 ft. - 2000

Negatives @ 11/2 - 1000

1000 ft. - 1000 ft. - 1000 ft. - 1000 ft.

1000 ft. - 1000 ft. - 1000 ft. - 1000 ft. - 1000 ft.



12/1/1911

12/1/1911

12/1/1911

12/1/1911

12/1/1911

12/1/1911

12/1/1911

Detail of the same inside foundation.

3 of 11



Ad. 191

2000

10/10/00

2000

January 2000

10/10/00

10/10/00

10/10/00

9 x 11



AA-2101

Self Property

Area 1, 100' x 100'

Becky Lane, 100' x 100', etc.

January 2000

100' x 100' x 100'

ERT 100' x 100' x 100'

View of Storage Units (100' x 100' x 100')

10 of 11



AA-2101

Dove Property

Anna Anna's N2

Belle Springs, N. W. 1/4

Section 2 N2

W. 1/2 S 14 E 27

1/2 Sec 21 N2 E 27

1/2 Sec 21 N2 E 27
1/2 Sec 21 N2 E 27

1/2