

AA-230A
MAGI #0203555605

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC SLAVE CABIN AT EDWARD COLLISON FARM
AND/OR COMMON

2 LOCATION

STREET & NUMBER West Side of Loch Haven Road, 1/4 Mile North of Jct. W/Rt. 214

CITY, TOWN Collison's Corner, Edge Water CONGRESSIONAL DISTRICT

STATE Maryland COUNTY Anne Arundel

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input checked="" type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input checked="" type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME Mayflower Mortgage Company Telephone #:

STREET & NUMBER

CITY, TOWN _____ STATE, zip code _____
VICINITY OF

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC. Anne Arundel County Courthouse

Liber #: Map #60
Folio #: AD # 1
Parcel #18

STREET & NUMBER 1 Liber/Folio #2446/21

CITY, TOWN Annapolis STATE Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE Maryland Historical Sites Inventory

DATE _____ FEDERAL _____ STATE _____ COUNTY _____ LOCAL _____

DEPOSITORY FOR SURVEY RECORDS Maryland Historical Trust

CITY, TOWN Annapolis STATE md.

44-2007

7 DESCRIPTION

CONDITION		CHECK ONE		CHECK ONE	
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE	<input type="checkbox"/> MOVED	DATE _____
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED			
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED				

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This log house is an integral member of the complex of 19th century buildings on the Collison farm. Each of them is decaying, this house and the smoke house being in the gravest condition. The tobacco barn has already collapsed.

The construction of the house is rough (the unplanned plank partitions and the exposed puncheon joists), is strictly utilitarian, and is plain to the point of starkness. Inside there remains no sign of embellishment or personal expression, except perhaps through the functional things that were hand-made, such as the door latches, but these too are devoid of decorative carving.

The house is one bay in length across both the facade (East) and rear (West). A late 19th century kitchen (now in ruins and overgrown) was added to the rear. Although the length and width (c.17' x c. 14') of this slave cabin are about the same as others, its height is much shorter, its front doorway measuring only 5' and the rooms less than 6'.

The cabin rests on stone pilings, hewn sills, and puncheon sleepers. The log walls are sheathed with board and batten attached by cut nails. The corners are diamond-notched; and the wide gaps between the logs are chinked with modern bricks, planks, and mortar. On the South gable end a narrow brick chimney has replaced the original, which may have been brick. Into the North gable wall was cut a small rectangular window opening with one sash of 2 over 2 lights; the sash and even the opening do not appear to be original. A small window opening was also sawn in the front door, but the door is not original, thus unless the original door had a window opening (which would have been uncommon), the ground floor had no windows, hence little light.

The interior consists of two small rooms, divided by a partition of planks vertically attached and cut by a circular saw. A low door connects the two rooms. Another doorway leads from the front room into the kitchen addition in the rear. In both rooms, the walls are whitewashed. In the front room the fireplace has been filled in with logs and a clay pipe installed for the wood stove. The mantle appears to be late 19th century and, though plain, has the most finished wood in the house. It is mill-made and may have been bought new or removed from another house.

In the northeast corner of the front room a steep and narrow stairway leads to the loft. It ascends directly over the end of the mantle and forcefully shows how cramped the quarters were. It resembles a ladder whose underside has been enclosed by horizontal planks. Indeed, it may have replaced a ladder, similar in usage to those at Blair's Purchase and East St. Mary's Manor in St. Mary's County. The treads are deeply worn, though not original. A plank door with a hand-made wooden latch closes off the stairway at the bottom landing

The frame loft is bisected into two rooms, corresponding to the two below. Each gable end has a window. The ceiling of turn of the century 1" x 4" planks covered the rafters, but where they had decayed, one could see that they had been mortised, tenoned, and pegged at the peak. The roof is covered more by honeysuckle than by the few remaining wood shingles.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

14-2304

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

George W. McDaniel

ORGANIZATION

Commission for Afro-American and Indian History and Culture

DATE

1/76

STREET & NUMBER

12 W. Madison St.

TELEPHONE

301-383-3648

CITY OR TOWN

Baltimore


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



AA-230



AA-230A

SLAVE CABIN AT EDWARD COLLISON FARM

George M^cDaniel

1976



AA-
230A

AA-30-U-a ^(map 24)
Log quarter at
"Edward Collision House"
East elevation

amb 3-75



AA-230A

SLAVE HOUSE AT COLLISON
FARM

near Collison's Corner, Md.

George McDaniel

1976



AA-230A

3. Collinson Farm Archeological Site (18 AN 574).

Anne Arundel County, Maryland.

Photo by Daniel Koski-Karell.

26 May 1986.

Negative at Maryland Historical Trust, Annapolis, MD.

View: Slave Cabin ruin; northern elevation; camera is facing south from northern corner of the cabin.

3 of 10.

2
494



AA-230A

4. Collinson Farm Archeological Site (18 AN 574).
Anne Arundel County, Maryland.
Photo by Daniel Koski-Karell.
26 May 1986.
Negative at Maryland Historical Trust, Annapolis, MD.
View: Slave Cabin ruin; southeast elevation; camera is
facing west.
4 of 10.

367