

AA-373

MARYLAND HISTORICAL TRUST
 21 STATE CIRCLE
 SHAW HOUSE
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
 Individual Structure Survey Form

SURVEY NUMBER: AA 373, 1400	
NEGATIVE FILE NUMBER:	
UTM REFERENCES: Zone/Easting/Northing	
U.S.G.S. QUAD. MAP:	
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE: 2F Res	
ORIGINAL USE: SF Res	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor: ()	
THEME:	
STYLE: Victorian Mansard	
DATE BUILT: 1897-1903	

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 97 Cathedral Street
COMMON NAME:
FUNCTIONAL TYPE: Res Map 30 Par 565
OWNER: Paul Panneton
ADDRESS: 3102 Tinder Place Bowie, MD 20715
ACCESSIBILITY TO PUBLIC: Yes (X) No () Restricted ()
LEVEL OF SIGNIFICANCE: Local (✓) State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone(X) Brick() Concrete() Concrete Block()
2. Wall Structure
 - A. Wood Frame: Post and Beam() Balloon(X)
 - B. Wood Bearing Masonry: Brick() Stone() Concrete() Concrete Block()
 - C. Iron() D. Steel() E. Other:
3. Wall Covering: Clapboard() Board and Batten() Wood Shingle() Shiplap()
 Novelty() Stucco() Sheet Metal() Aluminum() Asphalt Shingle()
 Brick Veneer() Stone Veneer() Asbestos Shingle(X)
 Bonding Pattern: Other:
4. Roof Structure
 - A. Truss: Wood(X) Iron() Steel() Concrete()
 - B. Other:
5. Roof Covering: Slate(X) Wood Shingle() Asphalt Shingle() Sheet Metal()
 Built Up() Rolled() Tile() Other:
6. Engineering Structure:
7. Other:

Appendages: Porches() Towers() Cupolas() Dormers(X) Chimneys(X) Sheds() Ells(X)
 Wings (X) Other:

Roof Style: Gable() Hip() Shed() Flat() Mansard(X) Gambrel() Jerkinhead()
 Saw Tooth() With Monitor() With Bellcast() With Parapet() With False Front()
 Other:

Number of Stories: 3
 Number of Bays: 3 x 3
 Approximate Dimensions: 20 x 50

Entrance Location: Right

THREAT TO STRUCTURE:
 No Threat (X) Zoning() Roads()
 Development() Deterioration()
 Alteration () Other:

LOCAL ATTITUDES:
 Positive() Negative()
 Mixed() Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-373

Excellent pedimented dormers with applied sunbursts in gables, on patterned slate false Mansard roof; good bracketed cornice with end consoles; molded window caps; full width front porch with square columns, transom lit door; asbestos shingles, including porch from rail to floor.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of false Mansard Second Empire, despite asbestos shingles at important corner location; contributes to streetscape; one of a pair with 99 Cathedral.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Lane() Woodland() Scattered Buildings()
- Moderately Built Up() Densely-Built Up(✓)
- Residential() Commercial()
- Agricultural() Industrial()
- Roadside Strip Development()
- Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc


DATE RECORDED:

Aug. 1983

Form 10-445
(5/62)

1. STATE Annapolis, Maryland COUNTY TOWN VICINITY STREET NO. 99, 97 Cathedral St. (2 bld) ORIGINAL OWNER ORIGINAL USE residences PRESENT OWNER PRESENT USE residences WALL CONSTRUCTION shingle (97 moderns) NO. OF STORIES two plus mansard attic	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY
	2. NAME DATE OR PERIOD 1880, - 90s STYLE Victorian ARCHITECT BUILDER
	3. FOR LIBRARY OF CONGRESS USE
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no <p>This pair are^{is} a fine Victorian couple. Though identical both add to the street and are worth preserving as a unit. Good examples of Victorian residences which are large and usable while presenting imposing street facades. They sit up on c3' basements, have front porches held up by 4 slim pillars and decorated with scalloping, 3 second storey windows (2/2), with modillioned, bracketed, and scalloped cornices. The outstanding feature of these houses is their "applied" mansard roof making up the 3rd storey. The mansard is of slate with a decorative diamond pattern running through the middle. There are two slightly projecting dormers on both with abstracted sun bursts on the pediment. Topped by small plain cornice - flat roof. Both basically unaltered except for 97's new siding, 99's brown shingling is original and is superb. <u>Very handsome.</u></p>	
	
5. PUBLISHED SOURCES (#author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.	7. PHOTOGRAPH 9. NAME, ADDRESS AND TITLE OF RECORDER William D. Morgan Columbia University New York City DATE OF RECORD June 22, 1967

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



SCALE IN FEET
0 50 100 200 300 400 500



AA 373
ANNAPOLIS HIST. DIST.

WASHINGTON

STREET

CALVERT STREET

NORTHWEST STREET

BLADEN STREET

ST. JOHN'S STREET

CARROLL STREET

COLLEGE

CHURCH CIRCLE

DEAN STREET

CATHEDRAL STREET

NORTHWEST STREET

STREET

STREET

SCHOOL ST

NORTH ST

STREET

ACTON

SHAW

SOUTH

DUKE

STATE CIRCLE

CHARLES

STREET

MAIL

1978



97 Cathedral

AA 373

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

NW Elevation/camera facing SE

J2 29