

MARYLAND HISTORICAL TRUST  
 21 STATE CIRCLE  
 SHAW HOUSE  
 ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
 Individual Structure Survey Form

SURVEY NUMBER: <u>AA 606</u>
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: <u>single Family Residence</u>
ORIGINAL USE: " " "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (x) Fair ( ) Poor: ( )
THEME:
STYLE: <u>vernacular-Annapolis Federal</u>
DATE BUILT: <u>1891-1897</u>

COUNTY: <u>Anne Arundel</u>
TOWN: <u>Annapolis</u>
LOCATION: <u>122 Market</u>
COMMON NAME:
FUNCTIONAL TYPE: <u>Res Map 33 Par 42</u>
OWNER: <u>McConnaughay Norma E &amp; James</u>
ADDRESS: <u>1902 Carrollton Rd.</u> <u>Annapolis, MD 21401</u>
ACCESSIBILITY TO PUBLIC: Yes (x) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE: Local (x) State ( ) National ( ) <input checked="" type="radio"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone ( ) Brick (x) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood Frame: Post and Beam ( ) Balloon (x)
  - Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other:
- Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
 Novelty ( ) Stucco (x) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
 Brick Veneer ( ) Stone Veneer ( ) Asbestos Shingle ( )  
 Bonding Pattern: \_\_\_\_\_ Other: \_\_\_\_\_
- Roof Structure
  - Truss: Wood (x) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (x)  
 Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (x) Towers ( ) Cupolas ( ) Dormers (x) Chimneys (x) Sheds ( ) Ells (x)  
 Wings ( ) Other:

Roof Style: Gable (x) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
 Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
 Other:

Number of Stories: 2½  
 Number of Bays: 2 Entrance Location: Right  
 Approximate Dimensions: 16x60

THREAT TO STRUCTURE: No Threat ( ) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:	LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:
--	---

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-606

Gabled dormer, heavy bracketed cornice with deep frieze; pedimented window and transom lit door caps; full width porch with later square pilasters, covered with stucco as is area below handrail.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Good example of late 19thC Vernacular with Italianate cornice, marred only by stucco and altered porch. Important to streetscape.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Lane( ) Woodland( ) Scattered Buildings( )  
 Moderately Built Up(✓) Densely Built Up( )  
 Residential( ) Commercial( )  
 Agricultural( ) Industrial( )  
 Roadside Strip Development( )  
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:

Aug. 1983



Part I, Item #3 Continued:

AA-606


The third floor was kept in its original condition except for the addition of wall plugs, refinishing the floor and painting.

The exterior of the house was not altered except for the installation of new gutters and downspouts and repairs to the laundry room area. The house was repainted inside and outside.

A small brick patio was uncovered in the yard at the rear of the house. This is being restored since the original patio had settled unevenly and if retained in its present condition would not be useful as a patio, but it would allow water to drain under the house and deteriorate the structure.

The back yard is enclosed on one side by a wooden fence and on the other side and across the back by an old brick wall, both of which are in good condition. The shrubbery in the back yard has not been disturbed although it appears to be of no historical significance.


FIRST FLOOR



2ND FLOOR



122 MARKET STREET  
DRAWING No 1



122 MARKET ST.  
DRAWING NO. 2

AA-606


0706062504

Form 10-445  
(5/62)



<p>1. STATE <b>Annapolis, Maryland</b>          COUNTY          TOWN VICINITY          STREET NO. <b>122 Market Street</b></p> <p>ORIGINAL OWNER          ORIGINAL USE <b>residence</b>          PRESENT OWNER <b>Highland</b>          PRESENT USE <b>residence</b>          WALL CONSTRUCTION <b>stucco</b>          NO. OF STORIES <b>two plus dormer attic</b></p>	<p>HISTORIC AMERICAN BUILDINGS SURVEY          INVENTORY</p> <p>2. NAME</p> <p>DATE OR PERIOD <b>Mid - Late 19th C.</b>          STYLE <b>Victorian - Federal</b>          ARCHITECT          BUILDER</p> <p>3. FOR LIBRARY OF CONGRESS USE</p>
<p>4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION <span style="float: right;">OPEN TO PUBLIC <input type="checkbox"/> NO</span></p> <p>122 Market Street is a Victorian Greco-Federal house, long and narrow, with one chimney and a triangular (6/6) dormer with returns. Below the simple wooden cornice is a row of scroll brackets. Two 2nd storey windows (6/6) are shuttered and have pedimental cap lintels. 1st storey window is larger version of same and doorway (with shutters) has same lintel treatment. Front porch has three square columns. Same scale, period, etc. as Nos. 128, 130, 134, 140, 142 Mark</p>	
<p>5. PHYSICAL CONDITION OF STRUCTURE</p>	<p style="text-align: right;"><u>good</u></p>
<p>6. LOCATION MAP (Plan Optional)</p> <p>7. PUBLISHED SOURCES (Author, Title, Pages)          INTERVIEWS, RECORDS, PHOTOS, ETC.</p>	<p>7. PHOTOGRAPH</p> <p>8. NAME, ADDRESS AND TITLE OF RECORDER</p> <p><b>William D. Morgan</b>  <b>Columbia University</b>  <b>New York City</b></p> <p>DATE OF RECORD <b>July 21, 1967</b></p>



SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



606  
ANNAPOLIS HIST. DIST.





122 Mkt

AA 606

Annapolis, Anne Arundel County  
Russell Wright July, 1982  
Maryland Historical Trust,  
Annapolis, Maryland

NE Elevation/camera facing SW

122 Mkt