MARYLAND HISTORICAL TRUST
21 STATE CIRCLE
SHAW HOUSE
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET
Individual Structure Survey Form

SURVEY NUMBER: AA-712, 713
NEGATIVE FILE NUMBER:
UTM REFERENCES:
Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:

COUNTY: Anne Arundel
TOWN: Annapolis
LOCATION: 71-75 West
COMMON NAME:
FUNCTIONAL TYPE: COMM Map 30 Par 55
OWNER:
ADDRESS: Rosenbloom Elerk & M
188 S Southwood Ave./Annapolis,MD 21401

ORIGINAL FORMAL NAME:
PRESENT USE: Office
ORIGINAL USE: Office
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent (x) Good ( )
Fair ( ) Poor: ( )

ACCESSIBILITY TO PUBLIC:
Yes (x) No ( ) Restricted ( )
LEVEL OF SIGNIFICANCE:
Local ( ) State ( ) National ( )

THEME:
STYLE: Contemporary
DATE BUILT:
1981

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone( )Brick( )Concrete( )Concrete Block(x)
2. Wall Structure
   A. Wood Frame: Post and Beam( )Balloon( )
   B. Wood Bearing Masonry: Brick( )Stone( )Concrete( )Concrete Block(x)
   C. Iron( ) D. Steel( ) E. Other:
3. Wall Covering: Clapboard( )Board and Batten( )Wood Shingle( )Shiplap( )
   Novelty( )Stucco( )Sheet Metal( )Aluminum( )Asphalt Shingle( )
   Brick Veneer(x)Stone Veneer( )Asbestos Shingle( )
   Bonding Pattern: Common Other:
4. Roof Structure
   A. Truss: Wood( )Iron( )Steel(x)Concrete( )
   B. Other:
5. Roof Covering: Slate( )Wood Shingle( )Asphalt Shingle( )Sheet Metal( )
   Built Up(x)Rolled( )Tile( )Other:
6. Engineering Structure:
7. Other:

Appendages: Porches( )Towers( )Cupolas( )Dormers( )Chimneys( )Sheds( )Ells( )
Wings ( )Other:
Roof Style: Gable( )Hip( )Shed( )Flat(x)Mansard( )Gambrel( )Jerkinhead( )
Saw Tooth( )With Monitor( )With Bellcast( )With Parapet(x)With False Front( )
Other:
Number of Stories: 3
Number of Bays: 6
Approximate Dimensions: 45 x 50
Entrance Location: Centered

THREAT TO STRUCTURE:
No Threat(x)Zoning( )Roads( )
Development( )Deterioration( )
Alteration ( )Other:

LOCAL ATTITUDES:
Positive( )Negative( )
Mixed( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-712
AA-713

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

No architectural significance.

REFERENCES:

MAP: (Indicate North In Circle)

SURROUNDING ENVIRONMENT:
Open Lane( )Woodland( )Scattered Buildings( )
Moderately Built Up( )Densely Built Up(✓)
Residential( )Commercial( )
Agricultural( )Industrial( )
Roadside Strip Development( )
Other:

RECORDED BY: Russell Wright

ORGANIZATION: Historic Annapolis, Inc

DATE RECORDED: Aug. 1983

AA-712

0207121411

Form 10-445 (5/62)

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

1. STATE Maryland
COUNTY
TOWN Annapolis VICINITY
STREET NO. ~~[illegible]~~ West St.
71-73
ORIGINAL OWNER
ORIGINAL USE Res./Commer., Commer.
PRESENT OWNER
PRESENT USE 71 Barber Shop-73 Restaurant
WALL CONSTRUCTION Stucco
NO. OF STORIES 71 3 + Dormer 73 - 3

2. NAME
DATE OR PERIOD Early-Mid 19th C
STYLE Federal
ARCHITECT
BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION — OPEN TO PUBLIC: yes

Though apparently two different periods, bldgs. 71-73 share a party wall (also connected to 69 and 75 West respectively). Though greatly altered, 71 perhaps as early as 1790, roof of metal with dormer, triangular with returns (6/6) 2nd and 3rd stories have 3 windows @ (6/6), but one on 2nd completly altered. Proportions are good.

73 is so altered as to be unrecognizable, but perhaps 1840 roof slope same as #71. Bldg. is important for it ties together this whole block of four buildings of different periods but homogenious re: scale, size, use etc. 71 definitely worth reconstruction and 73 worthy of preservation by location, but probably "old" by its own merit

5. PHYSICAL CONDITION OF STRUCTURE: fair

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER
William D. Morgan
Columbia University, N.Y., N.Y.

DATE OF RECORD June 16, 1967

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

AA-712
71-73 West St.
Sanborn Annapolis Apr. 1930-Mar. 1959
Annapolis
Anne Arundel County



AA - 712

ANNAPOLIS HIST. DIST.

N

SCALE IN FEET

0 50 100 200 300 400 500

ST. JOHN'S STREET

BLADEN STREET

COLLEGE

NORTH ST.

STATE CIRCLE

SCHOOL ST.

CARROLL STREET

CHURCH CIRCLE

NORTHWEST STREET

DUKE

CALVERT STREET

CATHEDRAL STREET

WASHINGTON

STREET

DEMO

LARKIN ST.

WATER ST

CITY GATE LANE

SHAW DEAN STREET

SHAW ST.

SOUTH

CHARLES STREET

SHAW STREET

ACTON

AA-712
71-73 West Street
Demolished, approximate location
Annapolis
Annapolis Quad



AA-713

0207131411

Form 10-445
(5/62)

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

1. STATE
COUNTY Annapolis, Maryland
TOWN VICINITY
STREET NO. 75 West Street

ORIGINAL OWNER
ORIGINAL USE commercial
PRESENT OWNER T.N. Phipps
PRESENT USE 7 Seas Bar/apartments
WALL CONSTRUCTION stucco
NO. OF STORIES ~~three~~

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

2. NAME

DATE OR PERIOD c.1835-40
STYLE Greek Revival
ARCHITECT
BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC yes

Three storey flat roofed building with unadorned but well-proportioned facade. Ground floor probably originally intended for store front of some sort, however, present bar front is obviously not original. 2nd storey windows, 6/1 (originally 6/6) are of equal size and are framed by a simple sash and flat wood lintel. The windows have louvered shutters, however, the shutters on the 2nd storey are smaller in size and may be replacements. The cornice is a simple wooden one overhanging c.1'. The front wall is painted red and the effect caused by the red and the black windows and shutters and white sash, is very striking. (The paint on the front is flaking, otherwise bldg. looks in fairly good shape. The bldg. goes back from from the street c. 100 + feet and the bldg. is larger than appears. The west side borders on Larkin Street and is unpainted stucco. The west side window sash is original but unpainted and in need of treatment. The building needs little to be very attractive integral part of streetscape.

5. PHYSICAL CONDITION OF STRUCTURE good



1885 Sanborn Map shows a frame grocery store on site

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER
William D. Morgan
Columbia University
New York City, N. Y.

DATE OF RECORD June 16, 1967

8-39

AA-713
75 West St.
Sanborn Annapolis Dec. 1913
Annapolis
Anne Arundel County




SCALE IN FEET
0 50 100 200 300 400 500
N
AA-713
ANNAPOLIS HIST. DIST.
WASHINGTON
STREET
CALVERT
STREET
NORTHWEST
STREET
BLADEN
STREET
ST. JOHN'S
STREET
CARROLL STREET
COLLEGE
LARKIN ST.
WATER ST.
CITY GATE LANE
CATHEDRAL
STREET
SHAW ST.
DEAN STREET
CHURCH CIRCLE
NORTH ST.
SCHOOL ST.
STATE CIRCLE
ACTON
STREET
SHAW
STREET
SOUTH
STREET
CHARLES
STREET
DUKE

AA-713
75 West Street
Demolished, approximate location
Annapolis
Annapolis Quad



LI DEPOT
FERRIS

71-75 West AA-712,713 AA
Annapolis, Anne Arundel County
Russell Wright July, 1982
Maryland Historical Trust,
Annapolis, Maryland
NW Elevation/camera facing SE

J1 15