

POPPLETON HISTORIC STUDY

B-2498

MAGI #0424985 504

<u>Block</u>	<u>Lot</u>	<u>Address</u>
185	69-61	1101-1117 W. Lexington Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
------------------	------------------	------------------	------------------	----------------

The 1851 map shows this block as scarcely built up. Most houses date between 1851-1860, and afterward.

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>			
A	Significant-save	good	fair	poor	bad
B	Quality-Indiv./groups-save	good	fair	poor	bad
<u>C</u>	Important to street/groups	good	fair	<u>poor</u>	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:


The west end of a long terrace. The houses are generally in poor condition but the essential form of the row survives and is worthy of rehabilitation. Numbers 1107-1115 are a matched group -- cornice is uniform, severe in design, dentils; only 1115 has original door surround. All have large back buildings seriously deteriorated. Number 1113 has round-headed windows at first and second floor which appear to be replacements for flat arches. Formstone door surround at 1111 is a blemish and should be removed.

Environmental context:

Numbers 1115, 1111, 1105 are vacant and lots at 1103 and 1101 are vacant. These houses are part of a long terrace of varied periods and style, but one possessed of interest and visual impressiveness. Excellent house-to-house scale and stands well against school and church across-street. Lexington Street is wide, busy; needs street trees.



B-2498
1101-1117 W. Lexington Street
Block 185 Lots 061-069
Baltimore City
Baltimore West Quad.



GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

