

POPPLETON HISTORIC STUDY

B-2504
MAG#0425045404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
185	111-117	116-128 N. Schroeder Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
	116 (c. 1860 or later)	118 126		
	120-124, 128			

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>			
A	Significant-save	good	fair	poor	bad
B	Quality-Indiv./groups-save	good	fair	poor	bad
(C)	Important to street/groups	good	fair	poor	(bad)
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:



Number 116 bears the marker "Kandscha Place." A pleasantly scaled terrace which should be rehabilitated. Number 126 has original store front. The condition of the structures is very bad, with cracked and bulging front walls -- the Schroeder Street side wall of 1001 W. Lexington is bulging hazardously.

Environmental context:


Numbers 122, 126 are vacant. Wide but not busy street; needs street trees. House-to-house scale is good and across-street is okay.



B-2504
 116-128 N. Schroeder Street
 Baltimore City
 Sanborn Maps



B-2504
116-128 N. Schroeder Street
Block 185 Lots 111-117
Baltimore City
Baltimore West Quad.



GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

