

POPPELTON HISTORIC STUDY

B-2518
MAGI #0425185 404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
187	49-44	111-121 N. Schroeder Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
	111-117	119, 121		

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
(B)	Quality-Indiv./groups-save	good fair poor bad
(C)	Important to street/groups	good (fair poor) bad
D	Insignificant/detrimental	good fair poor bad

Notable features:

Terrace of small houses which could be improved by more open space around and behind them.

(See sheet for numbers 105, 107)

Environmental context:

Number 121 is vacant. A wide street; no street trees (one is sick); house-to-house scale good and needs all to remain to maintain continuity.





B-2518

111-121 N. Schroeder Street

Baltimore City

Sanborn Maps

DEMOLISHED



Demolished

B-2518
111-121 N. Schroeder Street
Block 187 Lot 044-049
Baltimore City
Baltimore West Quad.

