

POTTRETON HISTORIC STUDY

B-2529

MAGI #0425295404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
188	43-40	112-118 N. Fremont Avenue

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

(1852-1860)

<u>Rating</u>	<u>Architectural</u>		<u>Condition</u>			
A	Significant-save	good	fair	poor	bad	
B	Quality-Indiv./groups-save	good	fair	poor	bad	
<u>C</u>	Important to street/groups	good	fair	<u>poor</u>	<u>bad</u>	
D	Insignificant/detrimental	good	fair	poor	bad	

Notable features:

The 1842 Directory shows a grocer, Davis, at the corner of Cove and Vine which might be number 112. The building does not appear on the 1852 map.


This is essentially good group because of the slipped arrangement of the facades to fit the line of Fremont Avenue. Number 118 has had its facade altered but it is worth rehabilitation. All have back buildings in poor repair.

Environmental context:

The row faces Fremont Avenue and Lexington Terrace homes. Numbers 112 and 118 are vacant. Noisy, busy street; needs trees. House-to-house scale good and intact group lends continuity.



B-2529
112-118 N. Fremont Ave.
Block 188 Lot 040-043
Baltimore City
Baltimore West Quad.



GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

