

POPPLETON HISTORIC STUDY

B-2690  
MAG140426905404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
237	1-11	868-884 W. Lombard Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
	872-880 868	870	882-884	

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
B	Quality-Indiv./groups-save	good fair poor bad
C	Important to street/groups	good fair poor bad
D	Insignificant/detrimental	good fair poor bad

Notable features:

Sachse view of 1869 and 1876 maps show a house set back on lots 882-884. This was presumably demolished, for the 1896 map shows this new building at the building line. Numbers 868 and 872/872½-874 are the oldest in the block; number 868 still has its original character and hipped roof, but the others have been formstoned. Numbers 878-880 are standard 1850's houses, severe cornice, door detailing typical, window basket metal work, good door surround at 880, which is a house of good proportions. Original doors remain at 880 and 878½. Numbers 878-878½ have a cornice in common; 878½ is vacant. The

(Continued on next sheet)

Environmental context:

(See next sheet)



## FOOTLETON HISTORIC STUDY (Continuation page)

<u>Block</u>	<u>Lot</u>	<u>Address</u>
257	1-11	868-884 W. Lombard Street

Notable features (continued):

facades of all except 876 are good, typical houses, though 876 has a fine promenade porch at the rear. Numbers 882-884 though later are serviceable and of reasonable though heavy and undistinguished design with glazed brick facade and stone sills.

Environmental context:

Very noisy, one-way street; some good street trees exist; more of same size should be planted. Houses across-street are also good, nice scale and together create a pleasant street except for incredible traffic noise.

B-2690  
868-884 W. Lombard Street  
Block 237 Lots 001-011  
Baltimore City  
Baltimore West Quad.



GIS data Courtesy of  
the City of Baltimore, MOIT/EGIS

