

POPPELTON HISTORIC STUDY

B-2691  
MAG1#0426915404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
237	12-21	886-898 W. Lombard Street

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
888 (rear) 888½	890-898	888 (front)		

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
B	Quality-Indiv./groups-save	good fair poor bad
<b>C</b>	Important to street/groups	good <b>fair poor</b> bad
D	Insignificant/detrimental	good fair poor bad

Notable features:

Houses at rear 888 and 888½ are a remaining example of early house type, a pair with pitched roof, ridge at right angle to the street, promenade porch. In poor repair but an interesting remnant; has two dormers. Originally there were two of these pairs, each freestanding.. Numbers 890-896 are examples of minimum speculative housing built for workers of the B. & O. and other shops nearby; almost all the windows still have 6/6 glass.



The front house at 888 is not on the Sachse view of 1869; it is late.

Environmental context:

(See comments for 868-884 W. Lombard.)



B-2691  
886-898 W. Lombard Street (884 1/2-886 demolished)  
Sanborn Maps



B-2691  
886-898 W. Lombard Street (884 1/2-886 demolished)  
Block 0237, Lots 012-021  
Baltimore City  
Baltimore West Quad

