

1. STATE COUNTY TOWN <i>Balt.</i> VICINITY <i>Ft. Sq. N.</i> STREET NO. <i>1302-1304-1306-1308-1310</i> ORIGINAL OWNER ORIGINAL USE <i>residences</i> PRESENT OWNER PRESENT USE <i>residences</i> WALL CONSTRUCTION <i>brick</i> NO. OF STORIES <i>3</i>	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <i>B-905</i>
	2. NAME DATE OR PERIOD <i>post Civil War</i> STYLE <i>Baltimore Row Home (Mitt.)</i> ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC *No*

This block row of 5 houses is composed of the fairly standard brick row (post Civil War?) house of this vicinity, however, they have the unusual interest of having a rather unusual, decorative ^{free-standing} porch design with square pillars and some strapwork, and marble base and steps. 1312 and 1316 have been torn down and these ⁵ should be retained as they form the half of the block on the north side of Franklin Square 1314, 1318, 1320, and 1322 are recorded here as they were originally part of continuous row - 1320-1322 boarded up - future uncertain.

5. PHYSICAL CONDITION OF STRUCTURE *Fair - Good*

Endangered	Interior	Exterior
------------	----------	----------

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER

DATE OF RECORD *11/5/68*


SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

0905

Form 445
(5/6)

1. STATE Maryland COUNTY Baltimore City TOWN Franklin Sq. VICINITY Franklin Sq. STREET NO. 1302-1304-1306-1308-1310 West ORIGINAL OWNER Lexington Street ORIGINAL USE residences PRESENT OWNER PRESENT USE residences WALL CONSTRUCTION brick NO. OF STORIES three	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY B-905 2. NAME DATE OR PERIOD post Civil War STYLE Baltimore Row House (Victorian) ARCHITECT BUILDER 3. FOR LIBRARY OF CONGRESS USE
---	---


4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION <p>This row of five houses is composed of the fairly standard brick row house (post Civil War) of the Union Square and Franklin Square vicinity. These particular houses have added interest in having a rather unusual decorative, free standing, porch design with square pillars and some strap work that is bent to form curves, etc. These houses have cellar sterys of marble and marble steps. 1312 and 1316 have been torn down and these five should be retained as they ferm half of the north side of Franklin Square. 1314, 1318, 1320, and 1322 should be noted here as they were originally part of a continuous row; 1320 and 1322 are beared up and it would appear as though their future was uncertain.</p>	OPEN TO PUBLIC no 5. PHYSICAL CONDITION OF STRUCTURE Endangered Interior Exterior Fair-good
---	---

6. LOCATION MAP (Plan Optional)	7. PHOTOGRAPH 
---------------------------------	---

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.	9. NAME, ADDRESS AND TITLE OF RECORDER William Mergan University of Delaware DATE OF RECORD Nov. 5, 1968
--	--

SUPPLEMENTAL INFORMATION AND PHOTOCOPYING MAY BE ADDED ON SHEET OF SAME SIZE

B-905
1302-1310 W. Lexington Street
Block 168 Lots 016-020
Baltimore City
Baltimore West Quad.





B-905

PHOTOGRAPH BY
WILLIAM D. MORGAN