

BA-1203

TURNER MILL DWELLING - Before 1850 - 204 Dairy Road, 0.15 mile west of York Road. Small, 2-story frame house in vernacular style, painted white, located east of the mill. Under the composition shingle covering is a log house according to statement by late owner Stuart Roser. Gable roof, good condition. House first appears on 1875 plat of Miss Georgetta C. Turner's property (in special bound volume of plats in clerk's office, Towson). House and mill were both on Lot No. 4. In a

lawsuit of 1884, Jasper Joyce, agent for the mill owner stated, "the house on the mill property is not very good". The property was advertised in the B.C. Union of January 21, 1888, with the notation, "It is further improved by a comfortable dwelling, stabling, and outbuildings." While owned by J. Frank Schultz, the 1918 tax ledger carried: "Dwelling 16 x 22, 2 stories, \$378." Owner:



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain March 1980
Neg Located at MHT
House from SW
Photo 1 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 1980
Neg Located at MHT
House from south, main facade
Photo 2 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain, October 30 1980
House from SW
Neg Located at MHT
Photo 3 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Living room, unusually low closet
door
Photo 4 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Living room, west window
Photo 5 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30, 1980
Neg Located at MHT
Living Room, stairway landing
Photo 6 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Kitchen, doors to enclosed porch and
to utility room
Photo 7 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Second story, front-west room,
 typical window frame
Photo 8 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Rough-hewn joists in basement
Photo 9 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain October 30 1980
Neg Located at MHT
Attic, hand-hewn rafter in original
 main block
Photo 10 of 11



Turner Mill Dwelling BA 1203
Baltimore County, Maryland
John McGrain March 1980
Neg Located at MHT
Frame stable from S
Photo 11 of 11