

Maryland Historical Trust

Maryland Inventory of Historic Properties number: BA-2671

Name: BO99/SHELBORNE RD. OVER HERBERT RUN

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

MARYLAND HISTORICAL TRUST	
Eligibility Recommended _____	Eligibility Not Recommended <u>X</u>
Criteria: <u> </u> A <u> </u> B <u> </u> C <u> </u> D	Considerations: <u> </u> A <u> </u> B <u> </u> C <u> </u> D <u> </u> E <u> </u> F <u> </u> G <u> </u> None
Comments: _____ _____ _____	
Reviewer, OPS: <u>Anne E. Bruder</u>	Date: <u>3 April 2001</u>
Reviewer, NR Program: <u>Peter E. Kurtze</u>	Date: <u>3 April 2001</u>

MARYLAND INVENTORY OF HISTORIC BRIDGES
HISTORIC BRIDGE INVENTORY
MARYLAND STATE HIGHWAY ADMINISTRATION/
MARYLAND HISTORICAL TRUST

MHT No. BA-2671

SHA Bridge No. B 099 Bridge name Shelbourne Road over Herbert Run

LOCATION:

Street/Road name and number [facility carried] Shelbourne Road

City/town 0.5 mi N of Sulphur Spring Road Vicinity X

County Baltimore

This bridge projects over: Road _____ Railway _____ Water X Land _____

Ownership: State _____ County X Municipal _____ Other _____

HISTORIC STATUS:

Is bridge located within a designated historic district? Yes _____ No X

National Register-listed district _____ National Register-determined-eligible district _____

Locally-designated district _____ Other _____

Name of district _____

BRIDGE TYPE:

Timber Bridge _____:
Beam Bridge _____ Truss -Covered _____ Trestle _____ Timber-And-Concrete _____

Stone Arch Bridge _____

Metal Truss Bridge _____

Movable Bridge _____:
Swing _____ Bascule Single Leaf _____ Bascule Multiple Leaf _____
Vertical Lift _____ Retractable _____ Pontoon _____

Metal Girder _____:
Rolled Girder _____ Rolled Girder Concrete Encased _____
Plate Girder _____ Plate Girder Concrete Encased _____

Metal Suspension _____

Metal Arch _____

Metal Cantilever _____

Concrete X :
 Concrete Arch _____ Concrete Slab X Continuous _____ Concrete Beam _____ Rigid
 Frame _____

Other _____ Type Name _____

DESCRIPTION:

Setting: Urban _____ Small town _____ Rural X

Describe Setting:

Bridge B0099 carries Shelbourne Road in an north-south direction over Herbert Run which flows in an easterly direction.

Describe Superstructure and Substructure:

Bridge B099 is a two span continuous reinforced concrete slab bridge on the original stone masonry abutments, wingwalls and pier. The length of each span is 16.0 feet and the overall length is 35.0 feet. The curb to curb width is 28.0 feet and the deck out to out width is 30.0 feet; the skew is 30 degrees. The 1993 inspection report described the bridge as in very good condition. The concrete parapets have minor cracks, the original stone masonry exhibits cracking within the mortar joints and is missing some stones. A full height crack in the N/W wingwall is due to a large tree stump in the fill behind the wingwall. The footing of the north abutment has 20 mil cracks, the south abutment has several hairline cracks with efflorescence in the footing. Both the abutment and the pier footings are scoured at water line exposing reinforcement at random locations. Minor cracking and efflorescence is evident on the original portions of the pier shaft. The bridge is not posted.

Discuss Major Alterations:

A 5 foot wide pedestrian bridge was added to the east side, consisting of steel channel stringers and timber decking. New parapets are jersey type. A new 2-span continuous slab was constructed in 1991.

HISTORY:

WHEN was bridge built (actual date or date range) 1920 Reconstructed 1948 1991

This date is: Actual X Estimated _____

Source of date: Plaque _____ Design plans _____ County bridge files/inspection form X

Other (specify) _____

WHY was the bridge built?

The need for a more efficient transportation network and increased load capacity in the decades following World War I.

WHO was the designer?

State Highway Administration

WHO was the builder?

Unknown

WHY was the bridge altered?

The bridge was reconstructed to ensure its structural adequacy.

Was this bridge built as part of an organized bridge-building campaign?

As part of an effort by the State to increase load capacity on secondary roads during the 1920s.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have National Register significance for its association with:

A - Events _____ B- Person _____
C- Engineering/architectural character _____

This bridge does not have National Register significance.

Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-04 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's road and bridge improvement programs mirrored economic cycles. The first road improvement program of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916 -1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war-related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920 to 1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund [with an equal sum from the counties] the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had become inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930s. Most improvements to local roads waited until the years after World War II.

With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer stated in 1906, "The general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do away with the further expense of the maintenance of expensive and dangerous wooden structures". Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

The creation of standard plans and a description of their use was first announced in the 1912-15 Reports of the State Roads Commission whereby bridges spanning up to 36 feet were to use standardized designs.

Published on a single sheet, the 1912 Standard Plans included those structures that were amenable to such an approach: slab spans, (deck) girder spans, box culverts, box bridges, abutments, and piers (State Roads Commission 1912). Slab spans, with lengths of 6 to 16 feet in two foot increments, featured a solid parapet that was integrated into the slab, with a roadway of 22 feet.

In the Report for the years 1916-1919, a revision of the standard plans was noted:

During the four years covered by this report, it has been found necessary to revise our standard plans for culverts and bridges, to take care of the increased tonnage which they have been forced to carry. Army cantonments...increased their operations several hundred per cent, and the brunt of the enormous truck traffic resulting therefrom, was borne by the State Roads of Maryland. In addition to these war activities, freight motor lines from Baltimore to Washington, Philadelphia, New York, and various points throughout Maryland, and the weight of many of these trucks when loaded, was in excess of the loads for which our early bridges were designed (State Roads Commission 1920:56).

Published on separate sheets, the new standard plans (State Roads Commission 1919) for slab bridges reveal that the major changes was an increase in roadway width from 22 feet to 24 feet and a redesign of the reinforcement. The slab spans continued to feature solid parapets integrated into the span. The range of span lengths remained 6 to 16 feet, but the next year (1920) witnessed the issue of a supplemental plan for a 20 foot long slab span (State Roads Commission 1920).

Based upon documentary evidence, Baltimore County and City were the early pioneers in concrete bridge building in Maryland. The first reinforced concrete bridge documented in Maryland was the bridge at Sherwood Station, built in 1903 by Baltimore County.

Evidence from historic maps suggests that almost all of the extant concrete slab bridges built before 1940 in Baltimore County replaced earlier bridges. With the exception of two bridges, all of these structures lie on roads whose alignments have changed little since the middle of the nineteenth century. The two exceptions are both located on Shelbourne Avenue in Arbutus. Shelbourne Avenue does not appear on the 1850 map of Baltimore County but does appear on the 1915 map. Both concrete slabs bridges on Shelbourne Avenue, however, were built after 1915. The evidence therefore suggests that these two bridges were also built to replace previous structures.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence to suggest that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

The bridge is not a significant example of its type.

Does the bridge retain integrity of important elements described in Context Addendum?

This character defining elements have not retained their integrity. There was significant reconstruction in 1948 and 1991. The slabs and parapets were replaced in 1991.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge will be necessary to evaluate its significance.

BIBLIOGRAPHY:

County inspection/bridge files X SHA inspection/bridge files _____

Other (list):

SURVEYOR:

Date bridge recorded 08/25/95 Name of surveyor _____

Organization/Address P.A.C. Spero & Company, Suite 412, 40 West Chesapeake Ave., Baltimore, MD

21204

Phone number (410) 296-1635

FAX number (410) 296-1670

Greiner, Inc.


**BALTIMORE COUNTY
1993 BRIDGE INSPECTION REPORT**

BA - 2671

BRIDGE NO. 099

SHELLBOURNE ROAD OVER HERBERT RUN


NO PHOTO
AVAILABLE



TYPICAL DECK SECTION

63

Maryland Historic Highway Bridges
Bridge Type CONCRETE SLAB
Map BALTIMORE SW, D-12
County BALTIMORE
Bridge # and Name B099
SHELBOURNE ROAD OVER HERBERT RUN
BT-2071



62



BA-2671

8099 SHELBOURNE ROAD OVER HERBERT RUN
BALTIMORE COUNTY, MD

C. HALL

8/98

MD SHPO

NORTH APPROACH

1 of 5



BA 2671

BO99 SHELBOURNE ROAD OVER HERBERT RUN

BALTIMORE CO., MD

C. HALL

8/98

MD SHPO

SOUTH APPROACH

2 of 5



BA-2671

8099 SHELBOURNE ROAD OVER HERBERT RUN
BALTIMORE Co., MD

C. HALL

MD SHPO

EAST ELEVATION

3 of 5



BA-2671

BO99 SHELBOURNE ROAD OVER HERBERT RUN

BALTIMORE Co., MD

C. HALL

8/98

MD SHPO

EAST SIDE -

4 of 5



BA-2671

BO 99 SHELBOURNE ROAD OVER HERBERT RUN

BALTIMORE CO., MD

C. HALL

8/98

MD SHPO

EAST SIDE

5 of 5