

CARR - 1165

7573 MIDDLEBURG ROAD

mid 19th c.

Detour

private

The stone house at 7573 Middleburg Road shows an example of the vernacular style for stone construction for this region. The building was part of the mill property and its style and scale suggest that it may have been the miller's house. It is a one story building with a raised basement and elevated first story. Architectural changes to the building during the 20th century, including the shed roofed dormer and galbe-front porch, give the appearance of a bungalow style structure today. This building is shown in the 1877 Atlas of Carroll County, Maryland as part of the mill property of Thomas S. Cover.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

m 34 p. 32

SURVEY NUMBER: CARR-1165

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Woodsboro

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good (x)
Fair () Poor ()

THEME:

STYLE:

DATE BUILT: mid 19th c.

COUNTY: CARROLL

TOWN: DETOUR

LOCATION: 7573 Middleburg Rd (11077)

COMMON NAME:

FUNCTIONAL TYPE: Residence

OWNER: Nancy C. Munshaur Angell
ADDRESS: tenant - Howard W. Franklin 775-2837

ACCESSIBILITY TO PUBLIC:
Yes () No (x) Restricted ()

LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone (x) Brick () Concrete () Concrete Block ()
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon ()
B. Wood Bearing Masonry: Brick () Stone (x) Concrete () Concrete Block ()
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (x) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (x)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (x) Towers () Cupolas () Dormers (x) Chimneys () Sheds ()
Ells () Wings () Other:

Roof Style: Gable () Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 1 1/2

Number of Bays: 3 x 1

Approximate Dimensions:

Entrance Location: center

THREAT TO STRUCTURE:

No Threat (x) Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive (x) Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Vernacular style stone structure that has 20th century additions (shed roof
 dormer and gable roof porch) that give it a bungalow style appearance.

Probably constructed as part of the ~~the~~ mid 19th century mill complex and may
 have been a miller's residence.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

contributing structure to the Detroit H. D.

REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas: part of T.F. Cover property

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
 Moderately Built Up (x) Densely-Built Up ()
 Residential () Commercial ()
 Agricultural () Industrial ()
 Roadside Strip Development ()
 Other:

RECORDED BY:

Joe Getty

ORGANIZATION:


Carr. Co. Dept. of Planning

DATE RECORDED:

3/31/86

WOODSBORO QUADRANGLE
MARYLAND
7.5 MINUTE SERIES (TOPOGRAPHIC)

5563 11 NW
(TANEYTOWN)



CARD-1165



1. CARR-1165 7573 Middleburg Road
2. Carroll Co., md
3. Joe Getty
4. April 1986
5. Md. Hist. Trust, Annapolis, Md
6. N & E elev. (Camera facing sw)
7. 1/1