

CARR - 1166

7569 MIDDLEBURG ROAD

mid 19th c.

Detour

private

The brick structure at 7569 Middleburg Road shows an example of the combination store and house type that was popular in this region during the 19th century. There are several examples of this in Detour. This example has a gable-front store design with stretcher bond brickwork. The residence was a wing to the structure built in common bond.

Architectural changes to the building during the 20th century, when it served as a bank, have altered the original storefront design. This building is shown in the 1877 Atlas of Carroll County, Maryland as store of J. W. Weant.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

m 34 p. 22

SURVEY NUMBER: CARR-1166

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Woodsboro

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Vacant Bank

ORIGINAL USE: Store & Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good ()
Fair (X) Poor ()

THEME:

STYLE:

DATE BUILT: mid-19th c.

COUNTY: CARROLL
TOWN: DETOUR
LOCATION: 7569 Middleburg Rd (MD77)
COMMON NAME: DeTour Bank
FUNCTIONAL TYPE: Residence / Store
OWNER: DeTour Bank
ADDRESS: 7569 Middleburg Rd
DeTour MD 21725
ACCESSIBILITY TO PUBLIC:
Yes () No (X) Restricted ()
LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon ()
B. Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Stretcher and Common Other:
4. Roof Structure
A. Truss: Wood (X) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:
Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells () Wings (X) Other:
Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:
Number of Stories: 2 1/2
Number of Bays: 2 x 3
Approximate Dimensions:
Entrance Location: Center

THREAT TO STRUCTURE:
No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other: Sandblasted Brick

LOCAL ATTITUDES:
Positive (X) Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Was built as a store with a wing for a residence. Store had a gable-front main facade. Alterations made during the 20th century while the structure served as a bank have altered the original storefront.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

contributing building to Detroit Hist. Dist.

REFERENCES:

1862 Martenet's Map:
1877 LG & S Atlas: J.W. Weart Store

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
Moderately Built Up Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:


Can. L. Dept of Planning

DATE RECORDED:

3/31/86

WOODSBORO QUADRANGLE
MARYLAND
7.5 MINUTE SERIES (TOPOGRAPHIC)

5563 II NW
(TANEYTOWN)



CARR-1166



1. CARR-1166 Old Detour Bank
7569 Middleburg Rd
2. Carroll Co, Md.
3. Joe Getty
4. April 1986
5. Md. Hist. Trust, Annapolis, Md
6. n & w elev (camera facing se)
7. 1/1