

CARR - 406

FRAME HOUSE

late 19th century

Fenby Farm Road
Westminster vicinity

private

The frame house is a representative late nineteenth century rural Victorian style farmhouse that was part of the Fenby Farm. Features typical of the period are its L-shaped plan, steeply-pitched gabled dormer, and porch bracket ornamentation. The interior woodwork consists mainly of molded door frames with corner blocks. The house has been uninhabited for several years and will probably soon be demolished.



DEPARTMENT OF PLANNING AND DEVELOPMENT
225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-406
 NEGATIVE FILE NUMBER:
 UTM REFERENCES:
 Zone/Easting/Northing
 U.S.G.S. QUAD. MAP: New Windsor
 PRESENT FORMAL NAME:

COUNTY: CARROLL
 TOWN: Westminster vicinity
 LOCATION: Fenby Farm Road
TAX MAP 45 Block 10 P-532
 COMMON NAME:
 FUNCTIONAL TYPE: Farmhouse
 OWNER: John D. Hannon
 ADDRESS: 113 West Main St.
Westminster, MD 21157
 ACCESSIBILITY TO PUBLIC:
 Yes () No (X) Restricted ()
 LEVEL OF SIGNIFICANCE:
 Local () State () National ()

ORIGINAL FORMAL NAME:
 PRESENT USE: developed
 ORIGINAL USE: Farmhouse
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent () Good ()
 Fair () Poor (X)
 THEME:
 STYLE:
 DATE BUILT: late 19th century

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
 2. Wall Structure
 A. Wood: Log () Post and Beam () Balloon (X)
 B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 C. Iron () D. Steel () E. Other
 3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
 Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
 Aluminum () Asphalt Shingle (X) Brick Veneer () Stone Veneer ()
 Bonding Pattern: Other:
 4. Roof Structure
 A. Truss: Wood (X) Iron () Steel () Concrete ()
 B. Other:
 5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
 Built Up () Rolled () Tile () Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
 Ells (X) Wings () Other: gabled dormer
 Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
 Saw Tooth () With Monitor () With Bellcast () With Parapet ()
 With False Front () Other:
 Number of Stories: 2 1/2
 Number of Bays: 3 x 2
 Approximate Dimensions:
 Entrance Location: center

THREAT TO STRUCTURE:
 No Threat () Zoning () Roads ()
 Development () Deterioration ()
 Alteration () Other:

LOCAL ATTITUDES:
 Positive () Negative ()
 Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:



RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

REFERENCES:

- 1862 Martenet's Map: } not shown
- 1877 LG & S Atlas: }

SURROUNDING ENVIRONMENT:

- Open Lane () Woodland () Scattered Buildings ()
- Moderately Built Up () Densely-Built Up ()
- Residential () Commercial ()
- Agricultural () Industrial ()
- Roadside Strip Development ()
- Other:


RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

U.S.G.S. MAP
NEW WINDSOR, MD.
1:24000 SCALE



650 00
FEET
4387
4386
4385
0.1 MI. TO U.S. 140
4384
35
FENBY 3.9 MI.
23 MI. TO U.S. 40
WESTMINSTER (UNCL. MD. 32) 0.3 MI.



1. CARR-406
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. South and east elevations (camera facing northwest)
7. 1/1

FRAME HOUSE