

CARR - 664

OLD WESTMINSTER ROAD HOUSE

mid 19th century

Westminster vicinity

private

Two-story, four-bay by two-bay house with an L-shaped plan. Contains two entrances in the central two bays in a manner found throughout German-settled regions of Pennsylvania, Maryland and Virginia. Exterior woodwork dates from the mid-to-late nineteenth century. The house is a representative farmhouse from the mid-to-late nineteenth century. It is currently uninhabited.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

2/18

SURVEY NUMBER: CARR-664

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: New Windsor

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: abandoned

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent () Good ()
Fair (X) Poor ()

THEME:

STYLE:

DATE BUILT: mid-19th century

COUNTY: CARROLL

TOWN: Westminster vicinity

LOCATION: east side of Old Westminster Road
1/2 mile north of Stone Chapel Road

COMMON NAME:

FUNCTIONAL TYPE: residence

OWNER: Clifford E. Still

ADDRESS: 232 Church St.
New Windsor MD 21776

ACCESSIBILITY TO PUBLIC:
Yes () No (X) Restricted ()

LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone (X) Brick () Concrete () Concrete Block ()
- Wall Structure
 - Wood: Log () Post and Beam (X) Balloon ()
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other
- Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum (X) Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells (X) Wings () Other:

Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 2

Number of Bays: 4x2

Approximate Dimensions: _____

Entrance Location: double entrance - 2
central bays

THREAT TO STRUCTURE:
No Threat () Zoning () Roads ()
Development () Deterioration (X)
Alteration () Other:

LOCAL ATTITUDES:
Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

German style two entrances - 2 central bays
mid-19th century woodwork or exterior details



RELATED STRUCTURES: (Describe)

none

STATEMENT OF SIGNIFICANCE:

representative mid-19th c. farmhouse

REFERENCES:

1862 Martenet's Map: 7

1877 LG & S Atlas:

map 51 p. 16

336/448

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
Moderately Built Up () Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:



U.S.G.S. MAP
NEW WINDSOR, MD.
1:24000 SCALE



1. CARR-664 Old Westminster Road
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. West elevation; camera facing east
7. 1/1