

CARR - 719

315 CRANBERRY ROAD

late 19th century

Westminster vicinity

private

315 Cranberry Road is a companion piece to 307 Cranberry Road. Both houses have the same design and ornamental gabled dormer. The porch on 315 Cranberry Road has been altered to serve as a balcony to the second floor, with a doorway located in the center bay of the second story.



DEPARTMENT OF PLANNING AND DEVELOPMENT
225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-719

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: residence

ORIGINAL USE: "

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent () Good (X)
Fair () Poor ()

THEME:

STYLE:

DATE BUILT: late 19th century

COUNTY: CARROLL

TOWN: Westminster vicinity

LOCATION: 315 Garberry Road

TAX MAP: 39 Block 21 P-639

COMMON NAME:

FUNCTIONAL TYPE: residence

OWNER: Glen Clarkson

ADDRESS: 315 Garberry Rd Westminster MD 21157

ACCESSIBILITY TO PUBLIC:
Yes () No (X) Restricted ()

LEVEL OF SIGNIFICANCE:
Local () State () National ()

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone (X) Brick () Concrete () Concrete Block ()
- Wall Structure
 - Wood: Log () Post and Beam () Balloon (X)
 - Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
 - Iron () D. Steel () E. Other
- Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum (X) Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood (X) Iron () Steel () Concrete ()
 - Other:
- Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells (X) Wings () Other:

Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 2 1/2

Number of Bays: 5 x 2

Approximate Dimensions: _____

Entrance Location: center

THREAT TO STRUCTURE:
No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:
Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

regional style with rural Victorian features -
gabled dome with round-arch window
full-length, one st. porch - serves as balcony to 2^d st

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

illustrates continuity in regional form amidst Victorian influences

REFERENCES:

1862 Martenet's Map:
1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
Moderately Built Up () Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

8/83

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



UN
DEPART
COR

GETTY SQUARE PA 21 MI
UNION MILLS 111 MI


320000

2.4 MI. TO MD. 496

57°30'

133

U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE



WESTMINSTER

High Sch

(BM 17)

755

Randon House Park

Cranberry Park

Filtration Plant

Substa
Cranberry Station

Reservoir

Tannery



1. CARR-719 315 CRANBERRY ROAD
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. South and west elevations
(camera facing northeast)
7. 1/1