

CARR - 740

615 LUCABAUGH MILL ROAD

late 19th century

Westminster vicinity

private

615 Lucabaugh Mill Road is a small house that appears to be a tenant structure from the Lucabaugh Mill complex. It does not appear on the 1877 map, and its exterior characteristics are from the post-1877 period. One unusual feature on the structure is the centrally-located patterned glass window on the first story of the main facade.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER:

CARR - 740

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

residence

ORIGINAL USE:

residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ()

Good (x)

Fair ()

Poor ()

THEME:

STYLE:

DATE BUILT:

late 19th century

COUNTY:

CARROLL

TOWN:

Westminster vicinity

LOCATION:

615 Lucabaugh Hill Road

TAX MAP 39 Block 15 P-360

COMMON NAME:

FUNCTIONAL TYPE:

residence

OWNER:

John L. Dell

ADDRESS:

615 Lucabaugh Hill Rd
Westminster MD 21157

ACCESSIBILITY TO PUBLIC:

Yes ()

No (x)

Restricted ()

LEVEL OF SIGNIFICANCE:

Local ()

State ()

National ()

GENERAL DESCRIPTION:

Structural System

- 1. Foundation: Stone (x) Brick () Concrete () Concrete Block ()
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon (x)
B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum (x) Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other:
4. Roof Structure
A. Truss: Wood (x) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (x)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (x) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells () Wings () Other:
Roof Style: Gable (x) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories:

2

Number of Bays:

2 x 1

Entrance Location:

side

Approximate Dimensions:

THREAT TO STRUCTURE:

No Threat () Zoning () Roads ()

Development () Deterioration ()

Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()

Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

unusually pattern glass window on 1st. of main facade

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

appears to be tenant house to Lucabough Hill property

REFERENCES:

1862 Martenet's Map: X
1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
Moderately Built Up (X) Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Tia Betty

ORGANIZATION:

DATE RECORDED:

6/83

U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE



TANEYTOWN 11 MI.
FRIZZELLBURG 3.9 MI.

(31)
(32)

4382

4381

4384

4385

4386



1. CARR-740 615 LUCABAUGH MILL ROAD
2. Carroll County, Maryland
3. Joe Getty
4. ^{Nov} November 1983
5. Md. Historical Trust, Annapolis, Md.
6. South and east elevations
(camera facing northwest)
7. 1/1